

**Recall Quarterly Report****17V-415****Manufacturer Name :** Toyota Motor Engineering & Manufacturing**NHTSA Recall No. / MFR Recall No. :** 17V-415 /HLC**Recall Subject :** Loose Lock Nut May Cause Tie Rod Separation**Owner Notification Beginning Date :** JUL 26, 2017**Owner Notification End Date:** JUL 26, 2017

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	JAN 18, 2019	2018-4	1,761	1,658	1	0
5	OCT 24, 2018	2018-3	1,761	1,640	1	0
4	JUL 26, 2018	2018-2	1,761	1,611	1	0
3	APR 27, 2018	2018-1	1,761	1,539	1	0
2	JAN 31, 2018	2017-4	1,761	1,435	1	0
1	JAN 31, 2018	2017-3	1,761	1,227	1	0

This Document Last Updated : JAN 28, 2019

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.