

# Recall Quarterly Report

# 17V-447

**Manufacturer Name :** Mercedes-Benz USA, LLC.  
**NHTSA Recall No. / MFR Recall No. :** 17V-447 / 2017090002  
**Recall Subject :** Left Front Axle Steering Knuckle may Fail  
**Owner Notification Beginning Date :** OCT 13, 2017  
**Owner Notification End Date:** OCT 13, 2017



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 3        | JUL 25, 2018    | 2018-2         | 110               | 82             | 0                 | 0             |
| 2        | APR 26, 2018    | 2018-1         | 110               | 63             | 0                 | 0             |
| 1        | JAN 20, 2018    | 2017-4         | 110               | 56             | 0                 | 0             |

This Document Last Updated : AUG 09, 2018

## Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.