

Recall Quarterly Report**17V-502**

Manufacturer Name : BMW of North America, LLC
NHTSA Recall No. / MFR Recall No. : 17V-502 /
Recall Subject : Right-Side Swingarm Pivot Pin Bolts May Loosen
Owner Notification Beginning Date : OCT 16, 2017
Owner Notification End Date: OCT 16, 2017



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	APR 22, 2019	2019-1	3,368	1,923	0	0
5	JAN 10, 2019	2018-4	3,368	1,859	0	0
4	OCT 30, 2018	2018-3	3,368	1,793	0	0
3	JUL 29, 2018	2018-2	3,368	1,571	0	0
2	APR 12, 2018	2018-1	3,368	1,292	0	0
1	JAN 26, 2018	2017-4	3,368	1,063	0	0

This Document Last Updated : APR 23, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.