

**Recall Quarterly Report****17V-537****Manufacturer Name :** Erwin Hymer Group North America, Inc.**NHTSA Recall No. / MFR Recall No. :** 17V-537 /**Recall Subject :** Exhaust may Melt Taillight Wiring**Owner Notification Beginning Date :** SEP 01, 2017**Owner Notification End Date:** SEP 01, 2017

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JAN 24, 2018	2017-4	195	37	0	1
1	OCT 27, 2017	2017-3	195	9	0	1

This Document Last Updated : JAN 26, 2018

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.