

Recall Quarterly Report**17V-625**

Manufacturer Name : Subaru of America, Inc.
NHTSA Recall No. / MFR Recall No. : 17V-625 /WTQ-76
Recall Subject : Subwoofer Wire may Overheat and Cause Fire
Owner Notification Beginning Date : OCT 31, 2017
Owner Notification End Date: OCT 31, 2017



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	APR 15, 2019	2019-1	9,178	5,965	23	147
5	JAN 21, 2019	2018-4	9,178	5,663	0	0
4	OCT 19, 2018	2018-3	9,178	5,393	0	0
3	JUL 12, 2018	2018-2	9,178	4,867	0	0
2	APR 20, 2018	2018-1	9,178	4,018	0	0
1	JAN 08, 2018	2017-4	9,178	2,639	0	0

This Document Last Updated : APR 18, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.