

**Recall Quarterly Report****17V-807**

**Manufacturer Name :** Mazda North American Operations  
**NHTSA Recall No. / MFR Recall No. :** 17V-807 /1917L  
**Recall Subject :** Driver Side Frontal Air Bag Inflator May Rupture  
**Owner Notification Beginning Date :** JAN 17, 2018  
**Owner Notification End Date:** JAN 17, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 26, 2018	2018-1	17,576	1,220	0	64

This Document Last Updated : APR 27, 2018

**Definitions :**

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.