

Recall Quarterly Report**17V-807**

Manufacturer Name : Mazda North American Operations
NHTSA Recall No. / MFR Recall No. : 17V-807 /1917L
Recall Subject : Driver Side Frontal Air Bag Inflator May Rupture
Owner Notification Beginning Date : JAN 17, 2018
Owner Notification End Date: JUL 10, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JAN 29, 2019	2018-4	17,576	5,034	246	53
3	OCT 29, 2018	2018-3	17,576	4,217	2,137	53
2	JUL 24, 2018	2018-2	17,576	2,161	0	64
1	APR 26, 2018	2018-1	17,576	1,220	0	64

This Document Last Updated : FEB 01, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.