OMB Control No.: 2127-0004

Part 573 Safety Recall Report

17V-033

Manufacturer Name: General Motors LLC

Submission Date: JAN 27, 2017 NHTSA Recall No.: 17V-033 Manufacturer Recall No.: 17017



Manufacturer Information:

Population:

Manufacturer Name: General Motors LLC

Address: 30001 VAN DYKE

MAIL CODE 480-210-2V WARREN MI

48090

Company phone: 5961733

Number of potentially involved: 214 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2016-2017 Chevrolet Suburban HD

Vehicle Type: LIGHT VEHICLES

Body Style : SUV Power Train : NR

Descriptive Information: Certain 2016 through 2017 Chevrolet Suburban Heavy Duty vehicles.

Production Dates: JUN 15, 2015 - NOV 10, 2016

Description of Noncompliance:

Description of the General Motors has decided that certain 2016-2017 model year Chevrolet

Noncompliance : Suburban Heavy Duty (HD) vehicles fail to conform to Federal Motor Vehicle

Safety Standard (FMVSS) 111, "Rearview mirrors." These vehicles were

assembled with a convex right-hand outside mirror. Because the weight rating for these heavy-duty vehicles exceeds 4,536 kg. (10,000 lbs.), FMVSS 111

requires non-convex, unit magnification (i.e., "flat") outside mirrors.

FMVSS 1: 111 - Rearview mirrors

FMVSS 2: NR

Description of the Safety Risk: If the driver of the vehicle is expecting a non-convex, unit magnification

mirror, a convex right-hand outside mirror could potentially confuse the driver as to the distance between the vehicle and objects to the right-rear of

the vehicle, increasing the risk of a crash.

Description of the Cause: GM's specification for the affected mirror in these heavy-duty vehicles did not

clearly designate flat glass. The supplier released the mirror with convex glass

rather than flat glass.

Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: Magna Mirrors of America

Address: 700 Southpark Drive

Newaygo MICHIGAN 49337

Country: United States

Chronology:

On November 18, 2016, a line operator at General Motors' Arlington, TX assembly plant discovered a Chevrolet Suburban HD vehicle with an incorrectly labeled right-hand outside mirror. A report was submitted in GM's Speak Up for Safety program on November 22, 2016 and, on November 23, 2016, a stop work order was issued for the affected vehicles. GM opened an investigation into the issue on December 5, 2016. Upon review of the issue with GM's regulatory experts, the investigator determined that the mirrors had been released with convex glass instead of non-convex, unit magnification glass, as required by FMVSS 111 for these heavy-duty vehicles. The issue was reviewed by GM's Open Investigation Review board on December 19, 2016. On January 5, 2017, GM's Safety and Field Action Decision Authority decided to conduct a non-compliance recall.

Description of Remedy:

Description of Remedy Program: Dealers will replace the affected mirror with a non-convex, unit

magnification mirror that meets FMVSS 111 requirements. Also, GM will include a new page for the owner's manual with the customer notification letter. Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under

warranty so reimbursement is not offered.

How Remedy Component Differs The replacement mirrors comply with the requirements of FMVSS 111.

from Recalled Component: Recalled Component Name: Mirror ASM-O/S RR view

Recalled Component Description: Outside, side rear-view mirror

Recalled Component Part Number: 23337726 and 23204330

Recalled Component Country of Origin: USA

Identify How/When Recall Condition GM suspended production and updated its specifications for these vehicles was Corrected in Production: to require right-hand outside mirrors with non-convex, unit magnification glass to be installed, as required by FMVSS 111. Production will resume on

2/6/2017 with the correct mirrors.

Recall Schedule:

Description of Recall Schedule: GM will provide owner notification dates when available.

Planned Dealer Notification Date: JAN 12, 2017 - JAN 12, 2017

Planned Owner Notification Date: NR - NR

Part 573 Safety Recall Report	17V-033	Page 3
* NR - Not Reported		
The information contained in this report was submitte	d pursuant to 49 CFR §573	