

Part 573 Safety Recall Report

17V-041

Manufacturer Name : Pratt Industries Inc.**Submission Date :** MAR 14, 2017**NHTSA Recall No. :** 17V-041**Manufacturer Recall No. :** EQ16-003**Manufacturer Information :**

Manufacturer Name : Pratt Industries Inc.

Address : 11365 Red Arrow Hwy
Bridgman MI 49106

Company phone : 269-465-4646

Population :

Number of potentially involved : 126

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2014-2014 Pratt Industries DC432LS9HL

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Trailers were fitted with axles which may have defective spindles. These axles were manufactured and supplied by SAF-Holland. Assigned Recall number # 15E-080.

Production Dates : APR 02, 2014 - JUN 16, 2014

VIN Range 1 : Begin : 1P9CP4323EB343951 End : 1P9CP4322EB343956 Not sequential

Vehicle 2 : 2014-2014 Pratt Industries DC432LS9

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Trailers were fitted with axles which may have defective spindles. These axles were manufactured and supplied by SAF-Holland. Assigned Recall number # 15E-080.

Production Dates : MAR 22, 2013 - DEC 31, 2013

VIN Range 1 : Begin : 1P9CP4327EB343659 End : 1P9CP4329EB343730 Not sequentialVIN Range 2 : Begin : 1P9CP4327EB343306 End : 1P9CP4325EB343353 Not sequential**Description of Defect :**

Description of the Defect : Trailers were fitted with axles which may have defective spindles. These axles were manufactured and supplied by SAF-Holland. Assigned Recall number # 15E-080.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This condition may result in the wheel end separating from the axle axle, possibly resulting in a crash.

Description of the Cause : Axles were produced out of specifications on the spindle wall thickness.

Identification of Any Warning that can Occur : Failure can occur without warning.

Supplier Identification :

Component Manufacturer

Name : SAF-Holland

Address : 1950 Industrial Boulevard
Muskegon MICHIGAN 49442

Country : United States

Chronology :

We will have to refer to SAF-Holland's chronology events referred in recall # 15E-080

Description of Remedy :

Description of Remedy Program : We will have to refer to SAF-Holland's chronology events referred in recall # 15E-080. Some of the details are still being discussed with the manufacturer of this defective axle, SAF-Holland.

How Remedy Component Differs from Recalled Component : Axles will have spindles produced as per SAF-Holland's specifications.

Identify How/When Recall Condition was Corrected in Production : We will have to refer to SAF-Holland's chronology events referred in recall # 15E-080.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAR 14, 2017 - MAR 30, 2017

Planned Owner Notification Date : MAR 14, 2017 - MAR 30, 2017

* NR - Not Reported