

Part 573 Safety Recall Report

17V-106

Manufacturer Name : Keystone RV Company

Submission Date : FEB 17, 2017

NHTSA Recall No. : 17V-106

Manufacturer Recall No. : 17-277



Manufacturer Information :

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 64

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2017 Dutchmen Coleman 2515RL

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Units with incorrect tire size printed as ST205/75R144C and incorrect rim size printed as 15X5J

Production Dates : NOV 17, 2016 - FEB 09, 2017

VIN Range 1 : Begin : 4YDT25120HM935198 **End :** 4YDT25127HM936624 Not sequential

Description of Noncompliance :

Description of the Noncompliance : It has been decided that the vehicles in this recall population fail to conform to the requirements of Part 567, "Certification." The vehicles subject to this recall may have been manufactured with the incorrect information on the Federal Identification Tag and Tire and Loading Information Label. The tag indicates the tire size is ST205/75R144C. The correct tire size is ST205/75R14C. The tag also indicates the rim size is 15X5J. The correct rim size is 14X5.5J.

FMVSS 1 : 567 - Certification

FMVSS 2 : NR

Description of the Safety Risk : Fails to conform to the requirements of Part 567, "Certification."

Description of the Cause : The incorrect tire size and rim size was printed on the label.

Identification of Any Warning that can Occur : Tire size on the Federal Identification Tag does not match information on the tire. Rim size on the Federal Identification Tag does not match information for the rim.

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

February 8, 2017 – Production noted the label was incorrect.
February 13, 2017 - Investigation concluded and determined the Federal Identification Tag would need to be replaced.

Description of Remedy :

Description of Remedy Program : The remedy is to replace the Federal Identification Tag.
How Remedy Component Differs from Recalled Component : The repair will conform to requirements of Part 567, "Certification."
Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.
Planned Dealer Notification Date : FEB 24, 2017 - FEB 24, 2017
Planned Owner Notification Date : FEB 24, 2017 - FEB 24, 2017

* NR - Not Reported