

Part 573 Safety Recall Report

17V-122

Manufacturer Name : Halcore Group, Inc.

Submission Date : FEB 27, 2017

NHTSA Recall No. : 17V-122

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Halcore Group, Inc.

Address : 3800 McDowell Road
Grove City OH 43123

Company phone : 999

Population :

Number of potentially involved : 55

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2017 Ford Type I

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : On certain type I vehicles with liquidSpring kneeling rear suspensions the rear brake banjo bolts should be inspected for any leakage and or looseness. If leakage or looseness is found, do not drive the vehicle or retighten the banjo bolt. The affected suspension systems have a serial number range 2003591-2004154. Continued vehicle use may result in partial or complete loss of rear service brakes which cause damage to the chassis and/or other vehicles, and possibly result in crash.

Production Dates : OCT 03, 2016 - JAN 09, 2017

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : On certain type I vehicles with liquidSpring kneeling rear suspensions the rear banjo bolts should be inspected for any leakage or looseness. If leakage or looseness is found, do not drive the vehicle or retighten the banjo bolts. The affected suspensions have a serial number range 2003591 - 2004154.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Continued vehicle use may result in partial or complete loss of rear service brakes which could cause damage to chassis and/or other vehicles and possibly result in crash.

Description of the Cause : Some LiquidSpring kneeling suspension kits have been supplied with (brake component) banjo bolts and an incompatible torque specification which could cause bolts to stretch or break during installation. the affected system component is the rear brake banjo bolts. The bolt may have been incorrectly

Identification of Any Warning that can Occur : torqued during the brake line retrofit process. Continued vehicle use could cause damage to the chassis and/or other vehicles, and possibly result in crash. Abnormal brake pedal feedback or reduced braking ability.

Supplier Identification :

Component Manufacturer

Name : LiquidSpring LLC
Address : 4899 E 400 SOUTH
Lafayette INDIANA 47905
Country : United States

Chronology :

Horton Emergency Vehicles received a notice from LiquidSpring LLC dated February 24, 2017 that some LiquidSpring kneeling suspension kits have been supplied with (rear brake component) banjo bolts and an incompatible torque specification which could cause bolt to stretch or break during installation.

Description of Remedy :

Description of Remedy Program : Rear brake banjo bolt may have been incorrectly torqued during the brake line retrofit process. The affected suspension systems have a serial number range 2003591- 2004154. If you have a 2017 F350,F450, or F550 chassis equipped with LiquidSpring suspension system within the above serial number range, please contact LiquidSpring to arrange service to have rear brake banjo bolts replaced, free of charge. The LiquidSpring contact information is as follows: Phone: 765-474-7816 Ext. 1 for customer service - 8:00AM-5:00PM EST service@liquidspring.com

How Remedy Component Differs from Recalled Component : Suspension Manufacture providing adequate torque specific banjo bolt for the brake assembly.

Identify How/When Recall Condition was Corrected in Production : Horton identified suspension kit inventory & pre delivered vehicle production.

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : MAR 01, 2017 - MAR 15, 2017
Planned Owner Notification Date : MAR 01, 2017 - MAR 15, 2017

* NR - Not Reported