

Part 573 Safety Recall Report

17V-140

Manufacturer Name : REV Recreation Group

Submission Date : MAR 03, 2017

NHTSA Recall No. : 17V-140

Manufacturer Recall No. : 170301REV



Manufacturer Information :

Manufacturer Name : REV Recreation Group

Address : 1031 U.S. 224 E

P.O. Box 31 Decatur IN 46733

Company phone : 800 509 3417

Population :

Number of potentially involved : 742

Estimated percentage with defect : 60 %

Vehicle Information :

Vehicle 1 : 2016-2016 Fleetwood Storm

Vehicle Type : LOW VOLUME VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Class A gasoline motorhomes, model 35 SK Only

Production Dates : SEP 03, 2015 - APR 06, 2016

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 2 : 2016-2017 Holiday Rambler Admiral XE

Vehicle Type : LOW VOLUME VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Only units equipped with Option # 331 Dual Air Conditioners.

Production Dates : FEB 18, 2016 - FEB 22, 2017

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 3 : 2016-2017 Fleetwood Flair

Vehicle Type : LOW VOLUME VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Only units equipped with Option # 331 Dual Air Conditioners

Production Dates : FEB 18, 2016 - FEB 21, 2017

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 4 : 2017-2017 Fleetwood Storm

Vehicle Type : LOW VOLUME VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Class A gas motorhomes

Production Dates : MAY 17, 2016 - FEB 22, 2017

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Vehicle 5 : 2017-2017 Holiday Rambler Vacationer XE

Vehicle Type : LOW VOLUME VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Class A motorhomes

Production Dates : MAY 24, 2016 - FEB 13, 2017

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Vehicle 6 : 2015-2015 Fleetwood Bounder Classic

Vehicle Type : LOW VOLUME VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Class A motorhomes

Production Dates : MAR 25, 2014 - MAY 12, 2015

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Vehicle 7 : 2015-2015 Fleetwood Terra Product Code 783

Vehicle Type : LOW VOLUME VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Class A motorhomes (Product code 783)

Production Dates : MAR 12, 2014 - JUN 10, 2015

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Vehicle 8 : 2015-2016 Fleetwood Terra Product Code 729

Vehicle Type : LOW VOLUME VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Class A motorhomes, Product Code 729

Production Dates : JAN 23, 2015 - NOV 24, 2015

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Description of Defect :

Description of the Defect :	On motorhomes affected by this recall, the external fuel pump and in-line fuel filter for the Onan 5.5 Kilowatt Generator may be improperly secured to the underside of the motorhome chassis.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	If the fuel pump, fuel filter, or connected fuel lines detach or are jarred loose, a fuel leak may result, posing the risk of fire or explosion in the presence of an ignition source.
Description of the Cause :	The external fuel pump and in-line fuel filter for the Onan 5.5 Kilowatt Generator may be have been secured to the underside of the motorhome chassis with nylon wire ties instead of proper insulated mounting clamps.
Identification of Any Warning that can Occur :	NR

Supplier Identification :

Component Manufacturer

Name :	NR
Address :	NR
	NR
Country :	NR

Chronology :

January 16, 2017: A REV RV dealer called REV Dealer Technical Support to inquire about the mounting location of the generator fuel pump on a Model Year 2017 Vacationer XE motorhome. The vehicle at the dealership was reported to be missing a fastener for the fuel pump bracket. The dealer was advised to use screws to secure the fuel pump's mounting bracket to the structural steel on the underside of the motorhome chassis.

January 17, 2017: Upon receiving notification of the dealer's call, REV RV Quality Control implemented a stop ship and began an investigation.

January 23, 2017: REV RV Compliance Engineering advised Rev Quality Control to research the 2017 Fleetwood Storm product as it shares its fuel system design for the Onan EFI 5.5 Kilowatt Generator with the 2017 Holiday Rambler Vacationer XE.

January 26, 2017: REV RV Dealer Technical Support received photos of the vehicle that the dealer called to inquire about on January 16. The photos indicated the 5.5 EFI generator's in-line fuel filter was improperly secured. The photos were forwarded to REV Compliance Engineering for review.

January 31: REV RV implemented a field investigation of 2017 Holiday Rambler Vacationer XE and 2017 Fleetwood Storm.

February 10, 2017: Engineering expanded the investigation to include Holiday Rambler Admiral XE and Fleetwood Flair,, equipped with Option 331, Dual Air Conditioners and an Onan EFI 5.5 Kilowatt Generator and external in-line fuel pump.

February 12, 2017: REV expanded its field investigation to include Model Year 2017 Fleetwood Flair and Model Year 2017 Holiday Rambler Admiral XE, in the effort to determine the scope of affected units.

February 28, 2017: Based on the review of the internal and field investigations, REV RV decided to conduct a voluntary recall of vehicles equipped with an Onan EFI 5.5 Kilowatt Generator and external in-line fuel pump.

Description of Remedy :

Description of Remedy Program : REV Recreation Group will notify owners, and REV dealers will inspect the mounting of the Onan EFI 5.5 Kilowatt generator's external fuel pump and in-line fuel filter, and if necessary, properly secure the fuel pump's mounting bracket to the chassis frame and secure the fuel filter lines with insulated clamps, as required. This service will be performed free of charge.

Pursuant to 49 CFR 573.6 (c)(8)(i), "Reimbursement", REV Recreation Group Inc. will reimburse owners for costs incurred for qualified repairs prior to notification according to REV's General Reimbursement Plan, revised 12/17/2015, and currently on file with the NTHSA.

How Remedy Component Differs from Recalled Component :

A properly secured Onan EFI generator external fuel pump's mounting bracket will be fastened to the chassis frame with proper fasteners. A properly installed in-line fuel filter will be secured with proper insulated clamps.

Identify How/When Recall Condition was Corrected in Production :

As of February 10, 2017, it was confirmed that units in production have the EFI generator's external fuel pump properly mounted to the chassis frame.

Recall Schedule :

Description of Recall Schedule :

REV intends to conduct dealer notifications via email and phone.
REV intends to conduct owner notifications via US mail.

Planned Dealer Notification Date :

APR 26, 2017 - APR 26, 2017

Planned Owner Notification Date :

APR 28, 2017 - APR 28, 2017

* NR - Not Reported