

Part 573 Safety Recall Report

17V-154

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** MAR 13, 2017**NHTSA Recall No. :** 17V-154**Manufacturer Recall No. :** N026**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 205

Address : 555 MACARTHUR BOULEVARD

Estimated percentage with defect : 100 %

MAHWAH NJ 07430

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2016-2016 LAND ROVER RANGE ROVER SPORT

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : 2016 MY Land Rover Range Rover Sport Vehicles in select VIN range

Production Dates : SEP 20, 2016 - OCT 24, 2016

VIN Range 1 : Begin : SALWG2PF4GA116357 End : SALWR2PF4GA123769

 Not sequential

VIN Range 2 : Begin : SALWR2KFXGA665031 End : SALWG2KF6GA665162

 Not sequential

Vehicle 2 : 2016-2016 LAND ROVER RANGE ROVER

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : 2016 MY Land Rover Range Rover Vehicles in select VIN range

Production Dates : SEP 22, 2016 - OCT 25, 2016

VIN Range 1 : Begin : SALGS2PFXGA314542 End : SALGS2PF2GA320108

 Not sequential

Description of Defect :

Description of the Defect : On certain 2016 MY Range Rover and Range Rover Sport vehicles, the front passenger airbag may not function properly due to a specification error in the mix of chemicals that are used for activation.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In the event of a crash of sufficient severity, the front passenger airbag may not deploy when required. Failure to deploy can lead to increased injuries to the passenger seat occupant.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NCS Pyrotechnie et Technologies SAS

Address : Rue de la Cartoucherie
BP 90010 Survilliers Fosses FOREIGN STATES

Country : France

Chronology :

See Document "JLR N026 Chronology".

Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to an approved Land Rover dealer who will replace the front passenger airbag.

There will be no charge to owners for this repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before May 1, 2017. Notifications to dealers will occur on March 14, 2017.

Planned Dealer Notification Date : MAR 14, 2017 - MAR 14, 2017

Planned Owner Notification Date : MAY 01, 2017 - MAY 01, 2017

* NR - Not Reported