

# Part 573 Safety Recall Report

# 17V-229

**Manufacturer Name :** Newmar Corporation**Submission Date :** APR 04, 2017**NHTSA Recall No. :** 17V-229**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

**Population :**

Number of potentially involved : 26

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2017-2017 Newmar King Aire

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, the 6 position connectors (1 on left side and 1 on right side) on the headlight harness could cause issues involving the glass dash. Both seals on the connector at the wire entry and the seal between the mating connector may have not been seated properly. This could allow water to infiltrate the connector, causing a back feed situation between turn signals and running lights. This could allow the turn signal side camera view over the speedometer and RPM displays. This could occur without warning, increasing the risk of a crash and/or property damage. Correction: The 6 position connector seals will be seated correctly.

Production Dates : JAN 22, 2016 - FEB 07, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

**Description of the Defect :** the 6 position connectors (1 on left side and 1 on right side) on the headlight harness could cause issues involving the glass dash. Both seals on the connector at the wire entry and the seal between the mating connector may have not been seated properly. This could allow water to infiltrate the connector, causing a back feed situation between turn signals and running lights. This could allow the turn signal side camera view over the speedometer and RPM displays.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** This could allow the turn signal side camera view over the speedometer and RPM displays.

Description of the Cause : NR  
Identification of Any Warning NR  
that can Occur :

## Supplier Identification :

### Component Manufacturer

Name : NR  
Address : NR  
NR  
Country : NR

## Chronology :

On 3/31/2017 the possibility of a defect was discovered on the glass dash of a King Aire. On 4/4/2016, Newmar is giving notice of defect to NHTSA.

## Description of Remedy :

Description of Remedy Program : NR  
How Remedy Component Differs NR  
from Recalled Component :  
Identify How/When Recall Condition NR  
was Corrected in Production :

## Recall Schedule :

Description of Recall Schedule : NR  
Planned Dealer Notification Date : JUN 03, 2017 - JUN 03, 2017  
Planned Owner Notification Date : JUN 03, 2017 - JUN 03, 2017

\* NR - Not Reported