

Part 573 Safety Recall Report

17V-254

Manufacturer Name : Rosenbauer Motors

Submission Date : APR 17, 2017

NHTSA Recall No. : 17V-254

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Rosenbauer Motors

Address : 5190 269th street

Wyoming MI 55092

Company phone : 6514621000

Population :

Number of potentially involved : 34

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2012-2017 Rosenbauer Commander

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Reyco Granning recall number 17E013

Production Dates : NOV 14, 2012 - FEB 17, 2017

VIN Range 1 : Begin : 54F2CB711EWM10579 **End :** 54F2DB620HWM11797 Not sequential

Description of Defect :

Description of the Defect : The Independent Front Suspension modules may contain loose ball joints.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The ball joints may separate from their mating part which could result in a partial loss of steering control.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :**Component Manufacturer**

Name : Reyco Granning
Address : 1205 Industrial Park Drive
Mt. Vernon MISSOURI 65712
Country : United States

Chronology :

Rosenbauer received notification of the recall on about April 1, 2017

Description of Remedy :

Description of Remedy Program : we will have our customers go to their respective dealers for an inspection and repair if necessary

How Remedy Component Differs from Recalled Component : no difference in the component. just proper installation procedures needed to be followed in production of the IFS modules

Identify How/When Recall Condition was Corrected in Production : see reyco recall 17E013

Recall Schedule :

Description of Recall Schedule : we will mail letters within the next three weeks

Planned Dealer Notification Date : MAY 08, 2017 - MAY 15, 2017

Planned Owner Notification Date : MAY 22, 2017 - MAY 29, 2017

* NR - Not Reported