

Part 573 Safety Recall Report

17V-286

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** APR 27, 2017**NHTSA Recall No. :** 17V-286**Manufacturer Recall No. :** H016**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 7

Address : 555 MACARTHUR BOULEVARD

Estimated percentage with defect : 100 %

MAHWAH NJ 07430

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2017-2017 JAGUAR XE

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : DIESEL

Descriptive Information : 2017 MY Jaguar XE vehicles in select VIN range

Production Dates : MAR 01, 2017 - MAR 20, 2017

VIN Range 1 : Begin : SAJAJ4BN4HCP14727 End : SAJAS4BN0HCP16861 Not sequential**Description of Defect :**

Description of the Defect : Jaguar Land Rover has identified a concern with certain 2.0L diesel engine Jaguar XE 2017 Model Year vehicles where the fuel return hose may leak. Increased fuel odor may be noticed and drivers may also observe liquid fuel puddles underneath the vehicle.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : It is possible that fuel may leak onto the road surface, which can present a skid hazard to other road users increasing the risk of a crash. Should leaking fuel come into contact with a sufficiently hot surface in the engine bay there will be an increased risk of fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

See Document "JLR H016 Chronology".

Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to a Jaguar authorized repairer who will replace the fuel return hose.

There will be no charge to owners for this campaign

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before June 19, 2017. Notifications to dealers will occur on May 2, 2017.

Planned Dealer Notification Date : MAY 02, 2017 - MAY 02, 2017

Planned Owner Notification Date : JUN 19, 2017 - JUN 19, 2017

* NR - Not Reported