

# Part 573 Safety Recall Report

# 17V-325

**Manufacturer Name :** Bison Coach, LLC

**Submission Date :** MAY 17, 2017

**NHTSA Recall No. :** 17V-325

**Manufacturer Recall No. :** 9011



## Manufacturer Information :

**Manufacturer Name :** Bison Coach, LLC  
**Address :** 804 SOUTH HIGBEE  
 MILFORD IN 46542  
**Company phone :** 999999999999

## Population :

**Number of potentially involved :** 192  
**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2016-2018 Bison Horse Trailers LAREDO, PREMIERE, RANGER, SILVERADO, TRAIL BOSS, TRAIL HAND

**Vehicle Type :** TRAILERS

**Body Style :** OTHER

**Power Train :** NR

**Descriptive Information :** It has been decided that certain travel trailers subject to this recall campaign may contain incorrect Gross Axle Weight Rating information listed on the certification label, due to a clerical error. Although the information on the vehicle labels may be incorrect, tires and axles of the correct size and rating were installed on the trailer.

**Production Dates :** DEC 11, 2015 - MAR 08, 2017

**VIN Range 1 : Begin :** 51Y3B6E27G2005975 **End :** 51Y3B6F28J2007482

Not sequential

## Description of Defect :

**Description of the Defect :** The incorrect GAWR was printed on the certification label.

**FMVSS 1 :** 567 - Certification

**FMVSS 2 :** NR

**Description of the Safety Risk :** If a trailer is labeled incorrectly, the potential for improper loading of the existing tires exists. Overloading of the trailer tires could result in poor handling and increased risk of an accident.

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

At the beginning of May 2017 manufacturing conducted a code change review of the data on GAWR and the tires and axles used, it was discovered that the incorrect GAWR was applied and printed on the certification label of certain trailers. This information was then verified and it was determined that the correct axles and tires were used, and the data was incorrectly applied to the certification label.

**Description of Remedy :**

Description of Remedy Program : The information was corrected in the computer system to pull the corrected information.

How Remedy Component Differs from Recalled Component : Production is now pulling correct information from within the data files.

Identify How/When Recall Condition was Corrected in Production : Was corrected during a scheduled data maintenance change

**Recall Schedule :**

Description of Recall Schedule : Owner letters to be mailed once approval of the retail letter is complete.

Planned Dealer Notification Date : MAY 30, 2017 - MAY 31, 2017

Planned Owner Notification Date : JUN 19, 2017 - JUN 20, 2017

\* NR - Not Reported