

# Part 573 Safety Recall Report

# 17V-327

**Manufacturer Name :** BMW of North America, LLC**Submission Date :** MAY 18, 2017**NHTSA Recall No. :** 17V-327**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : BMW of North America, LLC

Address : P.O. Box 1227

Westwood NJ 07675-1227

Company phone : 18005257417

**Population :**

Number of potentially involved : 24

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2017-2017 BMW X5 M

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : Approximately 20 potentially affected vehicles were equipped with a Tire Information Placard that may not fully conform to FMVSS 110.

Production Dates : APR 01, 2017 - APR 18, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2017-2017 BMW X6 M

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : Approximately 4 potentially affected vehicles were equipped with a Tire Information Placard that may not fully conform to FMVSS 110.

Production Dates : APR 04, 2017 - APR 12, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

**Description of Noncompliance :**

Description of the Noncompliance : The non-compliance involves the FMVSS 110 Tire Information Placard. Potentially affected vehicles were correctly equipped with 21-inch tires, but the FMVSS 110 Tire Information Placard states that the vehicles were equipped with 20-inch tires.

Although all other information on the placard is correct for the 21-inch tires, due to the incorrect tire size the labels do not conform to FMVSS 110 Section 4.3(d).

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : There is no safety risk as the tire pressure for both tire sizes are identical.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

On May 2, 2017, during a quality audit at a vehicle assembly plant, BMW became aware that the FMVSS 110 Tire Information Placard on a vehicle did not match the tires that were equipped on the vehicle.

A review of vehicle production information indicated that due to a data release error, labels containing information for 20-inch tires were allocated to certain vehicles equipped with 21-inch tires.

Additional reviews were conducted to determine the number and production range of potentially affected vehicles.

On May 11, 2017, BMW determined that the potentially affected vehicles do not conform to FMVSS 110 Section 4.3(d).

BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries related to this issue.

**Description of Remedy :**

Description of Remedy Program : The tire information placards on the affected vehicles will be replaced.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAY 18, 2017 - NR

Planned Owner Notification Date : JUL 10, 2017 - NR

\* NR - Not Reported