

# Part 573 Safety Recall Report

# 17V-385

**Manufacturer Name :** Starcraft RV**Submission Date :** JUN 19, 2017**NHTSA Recall No. :** 17V-385**Manufacturer Recall No. :** 9902356**Manufacturer Information :**

Manufacturer Name : Starcraft RV

Address : 903 South Main Street

P.O. Box 460 Middlebury IN 46540

Company phone : 800-945-4787

**Population :**

Number of potentially involved : 38

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2018-2018 Travel Trailer Launch Outfitter 24RLS (UT)

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : J2UT5051-5071, 5075-5081, 5084, 5087-5096, 5104-5116

ONLY UNITS WITH OPTION OF SLEEPER/TRI-FOLD SOFA OR THEATER SEATING

Production Dates : APR 05, 2017 - MAY 16, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Outlet between the sleeper/tri fold sofa or theater seating option and the kitchen sink is NOT GFI protected as required by NFPA Code violation NFPA 70 551.41C Ground Fault Circuit Interrupter Protection, Where the installed to serve the countertop surfaces and are within 6ft of any lavatory or sink.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Risk of electrical shock

Description of the Cause : The first run of the 2018 24RLS ( UT) electrical print was not correct showing this specific outlet as being GFI protected.

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : NR  
Address : NR  
NR  
Country : NR

### Chronology :

During routine Operations Camp Audit, 5-19-2017 - found a 2018 Launch Outfitter TT that did not pass GFI testing. Operations immediately started investigation and inspection of all same products on site - found only the 24RLS model (UT) with the specific option of a sleeper/tri/fold sofa OR theater seating was built with an outlet within 6ft of the kitchen sink, and required GFI protection. Investigation discovered that the electrical print for the 2018 UT did not show this outlet with the specified options as requiring the GFI protection. Print was revised, and is correct for the next run of the Launch Outfitter TT with specific option. 5-16-2017 Safety Committee reviewed all details of incident and decided a Recall was required.

### Description of Remedy :

Description of Remedy Program : Starcraft will replace the outlet with GFI protected outlet, free of charge.  
How Remedy Component Differs from Recalled Component : NR  
Identify How/When Recall Condition was Corrected in Production : Print updated immediately by Engineering, showing outlet as GFI protected.

### Recall Schedule :

Description of Recall Schedule : Starcraft is prepared to release recall notification upon receipt of NHTSA recall number.  
Planned Dealer Notification Date : NR - NR  
Planned Owner Notification Date : NR - NR

\* NR - Not Reported