

Part 573 Safety Recall Report

17V-444

Manufacturer Name : Keystone RV Company**Submission Date :** JUL 14, 2017**NHTSA Recall No. :** 17V-444**Manufacturer Recall No. :** 17-293**Manufacturer Information :**

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 137

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2016-2018 Keystone Avalanche 370RD

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Model 370RD

Production Dates : MAR 18, 2016 - MAY 19, 2017

VIN Range 1 : Begin : 4YDF37029GE760630 End : 4YDF37022GE760663 Not sequentialVIN Range 2 : Begin : 4YDF37024HE760021 End : 4YDF37024HE760875 Not sequentialVIN Range 3 : Begin : 4YDF37027JE760049 End : 4YDF37023JE760176 Not sequential**Description of Defect :****Description of the Defect :** It has been decided that the vehicles in this recall population may have an adjustment bolt for the kitchen slide that can come into contact with the tire.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the bolt comes into contact with the tire during travel, there is an increased risk of a tire blow out leading to the possibility of property damage and poor vehicle handling.**Description of the Cause :** The 370 model was built with too long of an adjustment bolt that allows the bolt to come into contact with the tire.**Identification of Any Warning that can Occur :** During pre-trip inspection there would be noticeable damage to the front tire under the kitchen slide.

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

June 21, 2017 – Production found that the adjustment bolt was in close proximity of the tire when the slide room was closed.

July 7, 2017 – Investigation concluded and determined that the bolt was too long and that an inspection of all 370RD models are needed to determine if repairs are needed.

Description of Remedy :

Description of Remedy Program : The remedy is to replace the incorrect length of adjustment bolt with a 3” bolt.

How Remedy Component Differs from Recalled Component : The shorter 3” bolt will allow proper clearance for the tire during travel.

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : JUL 27, 2017 - JUL 27, 2017

Planned Owner Notification Date : JUL 27, 2017 - JUL 27, 2017

* NR - Not Reported