

Part 573 Safety Recall Report

17V-558

Manufacturer Name : Corp. Micro Bird Inc.**Submission Date :** SEP 08, 2017**NHTSA Recall No. :** 17V-558**Manufacturer Recall No. :** 17-071-CUS**Manufacturer Information :**

Manufacturer Name : Corp. Micro Bird Inc.

Address : 3000, Rue Girardin

Drumondville, Quebec 00 J2E 0A1

Company phone : 819-477-2012

Population :

Number of potentially involved : 25

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2016-2016 Micro Bird G5

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Recalled vehicles are equipped with certain QS11 Convertible School Bus Seats manufactured by CE White/HSM Solution. The affected population is comprised of twelve (12) seat models: SC30RAA026, SC34LA8026, SC34RA8026, SC39LA6020, SC39LA6026, SC39LA8026, SC39LAA026, SC39RA3026, SC39RA6020, SC39RA6026, SC39RA8026, SC39RAA026,

Production Dates : MAY 01, 2016 - AUG 31, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : The QS11 Convertible Bus seats as manufactured by CE White/HSM Solutions contain a defect, which in the event of a rear collision, may result in occupant injury. These seats were manufactured with integral D-Ring mounting studs in the upper area of the seat back frame. The upper sea area where the mounting studs are located does not provide an acceptable padding surface between the seat occupant and the D-Ring mounting stud. HSM has determined that in a rear end collision by a larger vehicle, there is a potential increased risk of injury or death, to passenger seat occupant(s).

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In a rear crash event, the occupants head may contact the D-Ring mounting stud, resulting in a head injury. For this to occur, the occupant must be sitting in a position on the seat, which would place the back of the head in line with the D-Ring mounting stud during the crash event.

Description of the Cause : NR
Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : HSM Transportation Solutions
Address : 417 N. Kibler Street
New Washington OHIO 44854
Country : United States

Chronology :

Micro Bird Corporation Inc. received a safety recall notice from HSM on August 30th, 2017. The decision that the vehicles shall be recalled was made on September 6th

In fact, no report, accident, injury, fire or fatality has been reported to Micro Bird Corporation Inc. regarding this situation

Description of Remedy :

Description of Remedy Program : HSM will provide parts and a Service Repair Procedure "SRP" to mitigate this recall at no charge. It will be the responsibility of the lift owners to execute the mitigation

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : SEP 25, 2017 - OCT 31, 2017
Planned Owner Notification Date : OCT 02, 2017 - NOV 03, 2017

* NR - Not Reported