

Part 573 Safety Recall Report

17V-602

Manufacturer Name : C & M Trailers Inc.**Submission Date :** SEP 26, 2017**NHTSA Recall No. :** 17V-602**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : C & M Trailers Inc.

Address : 7501 West Ennis Ave

Ennis TX 75119

Company phone : (972)875-4528

Population :

Number of potentially involved : 58

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2015-2016 C&M Trailer Cargo trailers over 80 inches wide

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Cargo Trailers over 80 inches wide were produced with side marker lamps over 60 inches high

Production Dates : JUL 27, 2015 - DEC 31, 2016

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : The Cargo trailers being recalled had rear side marker lamps located higher than 60 inches and are not compliant with the requirements of FMVSS 108 for rear side marker lamps for trailers wider than 80 inches

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : This noncompliance may reduce the ability of other motorists to identify the correct length of a trailer

Description of the Cause : A worker in July 2015 switched the location of the side marker lamp from a compliant location to a non compliant location.

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

C&M traced the population of potentially non-compliant trailers to the time when a new-hire at C&M was assigned to work on building cargo trailers over 80 inches wide. His date of hire was in July of 2015 and his date of termination was January 2017. The cargo trailers over 80 inches wide produced during his time of hire were deemed potentially non-compliant.

Description of Remedy :

Description of Remedy Program : A letter will be sent to the dealers that sold these units as well as a letter to the owners for which addresses are available to advise and encourage them to bring their trailers into their dealer to have the rear side marker lamp placed within the specifications of FMVSS 108 for trailers over 80 inches wide

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : The placement of the side marker lamp was corrected after it was discovered. Starting in January 2017 Cargo trailers wider than 80 inches have the side marker lamps installed within between 15 and 60 inches from the ground.

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : OCT 23, 2017 - OCT 27, 2017
Planned Owner Notification Date : NOV 01, 2017 - NOV 10, 2017

* NR - Not Reported