

Part 573 Safety Recall Report

17V-606

Manufacturer Name : Silver Eagle Manufacturing Company**Submission Date :** SEP 28, 2017**NHTSA Recall No. :** 17V-606**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Silver Eagle Manufacturing Company

Number of potentially involved : 20

Address : 5825 NE Skyport Way
Portland OR 97218-1249

Estimated percentage with defect : 100 %

Company phone : 800-547-6792

Vehicle Information :

Vehicle 1 : 2018-2018 Silver Eagle VAST20W

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Trailer Axles & MPA/MTA Suspensions were found to have caliper bolts that did not meet torque specifications.

Production Dates : JUL 28, 2017 - JUL 28, 2017

VIN Range 1 : Begin : 1U3JX1113jbl20388 End : 1U3JX1113JBL20407 Not sequential**Description of Defect :**

Description of the Defect : Meritor, Inc. has decided that a defect which relates to motor vehicle safety exists in certain Meritor Trailer Axles & MPA/MTA Suspensions. They have found to have caliper bolts that did not meet torque specifications.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The failure mode for this issue is a partial or full detachment of the affected brake caliper.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :**Component Manufacturer**

Name : Meritor Heavy Vehicle Systems
Address : 2135 West Maple Road
Troy MICHIGAN 48084
Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported