

Part 573 Safety Recall Report

17V-614

Manufacturer Name : Trail King Industries, Inc.

Submission Date : OCT 02, 2017

NHTSA Recall No. : 17V-614

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Trail King Industries, Inc.

Address : PO BOX 1064

Mitchell SD 57301

Company phone : 999

Population :

Number of potentially involved : 2

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Trail King OLB844NG-HH

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Trail King has only produced two trailers using the Meritor axles specified in the recall. All other trailers used a different brand of axles.

Production Dates : JUN 20, 2017 - JUN 26, 2017

VIN Range 1 : Begin : 1TKL04988JW064498 **End :** 1TKL0498XJW064499 Not sequential

Description of Defect :

Description of the Defect : Trailer axles & MPA/MTA suspensions found to have caliper bolts that did not meet torque specifications. The suspect axles & suspensions were assembled at the Meritor Frankfort site between January 1, 2017 and August 4, 2017.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Failure of the brake caliper would likely cause a reduction in braking performance and increase in stopping distance but not loss of control.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Meritor
Address : 2135 West Maple Road
Troy MICHIGAN 48084-7121
Country : United States

Chronology :

Trail King completed the two OLB844NG-HH trailers using Meritor axles and suspensions on June 20, 2017 and June 26, 2017. On September 26, 2017 we received a recall notification from Meritor referencing Meritor recall number C17AB and NHTSA recall number 17E049. The recall instructed Trail King as an OEM to conduct a safety recall to correct the issue. We verified the axle serial numbers matched our records and we decided on September 28, 2017 Trail King will conduct a recall to correct the issue.

Description of Remedy :

Description of Remedy Program : The vehicle will be inspected at no charge to the customer. Meritor will supply necessary parts at no charge if needed and cover 3.75 hours per axle depending on what if any parts need replaced.

How Remedy Component Differs from Recalled Component : Trail King will inspect and repair the vehicle axles in accordance to Meritor instructions provided.

Identify How/When Recall Condition was Corrected in Production : June 26, 2017. Trail King only used these axles on two trailers.

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : OCT 03, 2017 - OCT 13, 2017
Planned Owner Notification Date : OCT 09, 2017 - OCT 13, 2017

* NR - Not Reported