

Part 573 Safety Recall Report

17V-624

Manufacturer Name : Transportation Collaborative, Inc.

Submission Date : OCT 30, 2017

NHTSA Recall No. : 17V-624

Manufacturer Recall No. : 17e045



Manufacturer Information :

Population :

Manufacturer Name : Transportation Collaborative, Inc.

Address : 7 Lake Station Road

Warwick NY 10990

Company phone : 845-988-0419

Number of potentially involved : 21

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2015-2016 Transtech Bus Chevy, SST, ST.Aero and SST FLR

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : The recall affects vehicles that are equipped with QS11 model series convertible seats produced by CE / HSM Solutions. The vehicles involved are being identified through the purchase order used to procure the seats per vehicle.

Vehicles that are not equipped with QS11 model Series Convertible seats are not included in the recall population.

Production Dates : OCT 01, 2014 - DEC 31, 2016

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : Pre recall number 17E045 notified by CE White / HSM solutions. Vehicles equipped with QS11 Convertible School Bus Seats as Manufactured by CE White/ HSM Solutions contain a defect, which in the event of a rear collision, may result in occupant injury. These seats were produced with integrated D-ring mounting studs in the upper area of the seat back frame. The upper seat area where the seat occupant and the D-ring mounting stud. HSM has determined that in a rear impact by a larger vehicle the occupants head may come in contact with the D-ring, resulting in a head injury.

FMVSS 1 : 207 - Seating systems

FMVSS 2 : NR

Description of the Safety Risk : The upper seat area where the seat occupant and the D-ring mounting stud. HSM has determined that in a rear impact by a larger vehicle the occupants head may come in contact with the

Description of the Cause : NR

Identification of Any Warning that can Occur : There is no audible or visual warning, which would precede an event. All Seat models indicated in the notice submitted and CE White/ HSM solutions are presumed to contain the defect and must be repaired.

Supplier Identification :

Component Manufacturer

Name : HSM Solutions/ CE White
Address : 417 N. Kibler St
New Washington OHIO 44854
Country : United States

Chronology :

On August 28th , Transtech Bus received a recall notice 17E045 from CE White /HSM Solutions outlining the affected seats models . These vehicles are being identified by the purchase orders used to purchase the affected seats.

Description of Remedy :

Description of Remedy Program : The remedy for the recall will consist of requesting the SRP 1701-001 repair kit provided by HSM Solutions which includes a foam block that needs to installed to protect the occupant from the d-ring

How Remedy Component Differs from Recalled Component : The part numbers to be used for the recall under SRP 1701-001 are as follows:
Axle guard Part# 800-532 and Re-bond Foam Block- Part# 203-381

Identify How/When Recall Condition was Corrected in Production : Refer to recall 17E-045.

Recall Schedule :

Description of Recall Schedule : The vehicle poluplation is under investiagtion using the PO's used to purchase the affected seats between 2014 and 2016. The population will be identified and completed no later then October 19th 2017. Dealer and customer will be notified of the recall no later then October 27th 2017

Planned Dealer Notification Date : OCT 27, 2017 - OCT 30, 2017

Planned Owner Notification Date : OCT 27, 2017 - OCT 30, 2017

* NR - Not Reported