

Part 573 Safety Recall Report

17V-646

Manufacturer Name : West-Mark

Submission Date : OCT 12, 2017

NHTSA Recall No. : 17V-646

Manufacturer Recall No. : C17AB



Manufacturer Information :

Manufacturer Name : West-Mark

Address : PO Box 100

Ceres CA 95307

Company phone : 999

Population :

Number of potentially involved : 1

Estimated percentage with defect : 100 %

Vehicle Alterer Information :

Vehicle 1 : 2010-2011 West-Mark 2TANCX3A

Descriptive Information : only purchased one suspension in this date code

Production Dates : OCT 01, 2010 - SEP 30, 2011

Description of Defect :

Description of the Defect : Specific torque on bolts holding caliper carrier left factory unchecked

FMVSS 1 : NR

FMVSS 2 : 121 - Air brake systems

Description of the Safety Risk : Calipers may come loose in service

Description of the Cause : NHTSA Recall 17E049 see Meritor TP-15141

Identification of Any Warning that can Occur : unknown

Supplier Identification :

Component Manufacturer

Name : Meritor

Address : NR

Troy MICHIGAN

Country : United States

Chronology :

Meritor file # C17AB

Description of Remedy :

Description of Remedy Program : Re torque bolts by Meritor TP-15141 Technical Bulletin or Contact West-Mark / Meritor OnTrac Customer Service Center for replacement parts if needed.

How Remedy Component Differs from Recalled Component : All MPA or MTA suspensions with date code 1/1/17 to 8/4/17

Identify How/When Recall Condition was Corrected in Production : unknown

Recall Schedule :

Description of Recall Schedule : Owner notification only

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : OCT 23, 2017 - NOV 23, 2017

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

* NR - Not Reported