

Part 573 Safety Recall Report

17V-702

Manufacturer Name : Crysteel Manufacturing Inc

Submission Date : NOV 06, 2017

NHTSA Recall No. : 17V-702

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Crysteel Manufacturing Inc

Address : 52182 Ember Road

Lake Crystal MN 56055

Company phone : 519-2933

Population :

Number of potentially involved : 9

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2017 Isuzu NRR-Series

Vehicle Type : LOW VOLUME VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Production run of 9 units of the same specifications. Crysteel Manufacturing installs the dump body on the chassis.

Production Dates : MAR 20, 2017 - APR 07, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Driveshaft comes loose at the rear u-joint

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Drive shaft could become detached from vehicle

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : Crysteel Truck Equipment

Address : 52248 Ember Road

Lake Crystal MINNESOTA 56055

Country : United States

Chronology :

First failure date June 23rd, 2017

Second failure was on October 23rd, 2017

Owners were all notified by phone and email to stop operating the vehicle and take out of service November 2nd, 2017

Description of Remedy :

Description of Remedy Program : Drive shaft could become detached from vehicle

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Owners were all notified by phone and email to stop operating the vehicle and take out of service November 2nd, 2017

Planned Dealer Notification Date : NOV 03, 2017 - NOV 03, 2017

Planned Owner Notification Date : NOV 03, 2017 - NOV 03, 2017

* NR - Not Reported