

Part 573 Safety Recall Report

17V-725

Manufacturer Name : Honda (American Honda Motor Co.)**Submission Date :** NOV 17, 2017**NHTSA Recall No. :** 17V-725**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Honda (American Honda Motor Co.)

Address : 1919 Torrance Blvd.

Torrance CA 90501

Company phone : 1-888-234-2138

Population :

Number of potentially involved : NR

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2011-2011 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : JAN 01, 1990 - JAN 01, 1990

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2012-2012 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : JAN 01, 1990 - JAN 01, 1990

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2013-2013 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN

Descriptive Information : range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : JAN 01, 1990 - JAN 01, 1990

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 4 : 2014-2014 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : JAN 01, 1990 - JAN 01, 1990

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 5 : 2015-2015 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : JAN 01, 1990 - JAN 01, 1990

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 6 : 2016-2016 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : JAN 01, 1990 - JAN 01, 1990

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 7 : 2017-2017 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : JAN 01, 1990 - JAN 01, 1990

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : The second row outboard (outer) seats can be placed in two positions, standard and wide. The rear outboard seat strikers have a collar to define the two set positions. If an outboard seat is positioned over the collar while attaching the seat to the vehicle floor, the seat will not latch properly to the seat striker.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : An unlatched second row outboard seat could tip forward during moderate to heavy braking increasing the risk of injury to an occupant, including a child seated in a LATCH child seat.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Please refer to the attached document titled 'Chronology.pdf'.

Description of Remedy :

Description of Remedy Program : Registered owners of affected vehicles will receive a notification letter in the mail that will contain detailed instructions for installing/positioning second row outer seats and confirming that they are securely latched. Similar information will be provided via online and social media channels prior to the notification. Once a final remedy is determined and the necessary parts are available, Honda will send a second letter to registered owners asking them to bring their vehicles to a dealership for a free repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Owners will be notified by mail on or about December 18, 2017.

Planned Dealer Notification Date : NOV 18, 2017 - NR

Planned Owner Notification Date : DEC 18, 2017 - NR

* NR - Not Reported