

Part 573 Safety Recall Report

17V-808

Manufacturer Name : Forest River, Inc.**Submission Date :** DEC 15, 2017**NHTSA Recall No. :** 17V-808**Manufacturer Recall No. :** 03-0599**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Population :

Number of potentially involved : 25

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Forest River, Inc. SANDPIPER - SAF369SAQB and SAF373REBH

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : On December 12, 2017, Forest River's Sierra and Sandpiper Divisions conducted an audit of three new vehicles in manufacturing and found an error associated with the vehicles' Federal Placard information. The recall includes all affected vehicles manufactured prior to the audit and correction in which took place the week of December 12, 2017.

Production Dates : SEP 12, 2017 - NOV 21, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2018-2018 Forest River, Inc. SEIRRA - SEF357RE

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : On December 12, 2017, Forest River's Sierra and Sandpiper Divisions conducted an audit of three new vehicles in manufacturing and found an error associated with the vehicles' Federal Placard information. The recall includes all affected vehicles manufactured prior to the audit and correction in which took place the week of December 12, 2017.

Production Dates : NOV 21, 2017 - DEC 08, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : The Federal Placard incorrectly states the tire PSI as 110, whereas the tires' PSI should be 95. The Tire, rim designation and load rating are not affected.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : 567 - Certification

Description of the Safety Risk : If tires are inflated to the incorrect PSI it may lead to uneven wear on the tire, pre-mature tire failure which will reduce the handling of the vehicle which may lead to loss of control, increasing the risk of a crash.

Description of the Cause : A data entry error occurred when entering the parameters of the affected tire's PSI.

Identification of Any Warning that can Occur : None

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On December 12, 2017, Forest River's Sierra and Sandpiper Divisions conducted an audit of three new vehicles in manufacturing and found an error associated with the vehicles' Federal Placard information. An investigation was initiated and on December 15, 2017, Forest River's Corporate Committee decided to conduct a recall to address this issue.

Description of Remedy :

Description of Remedy Program : Forest River will provide new Federal Placards, free of charge to both Owners and Dealers.

What is the Forest River Customer Service Phone Number? (574)
534-4574

How Remedy Component Differs from Recalled Component : The Federal Placards will be printed with the revised information to reflect accurate data; the Federal Placard will be the same part number.

Identify How/When Recall Condition was Corrected in Production : The condition was corrected through a data entry revision during the week of December 12, 2017.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : FEB 12, 2018 - FEB 12, 2018

Planned Owner Notification Date : FEB 12, 2018 - FEB 12, 2018

* NR - Not Reported