



Publish Date: July 31, 2017 **Due Date:** August 1, 2017

Information: HB5Z-1104-C Stop Sale

To: FCS Customer

Attention: Product Manager and Quality Manager

ACTION REQUESTED

FCS is issuing a Stop Sale of HB5Z-1104-C hub and bearing assemblies. The affected parts should be held pending further direction from FCS Quality Department.

Summary

The part number change led to parts being shipped with the incorrect application. HB5Z-1104-C is **not** compatible with 2WD rear axles.

Vehicles Affected

2011 through 2017 Ford Explorer 2WD

Inquiries

Contact FCS Quality Department Manager for further inquiries

Marc Moncion
Quality Manager
Ford Component Sales
mmoncio1@ford.com
Work: 313-317-7248