

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS4956  
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 14, 2019

Subject: GM Dealers Servicing Saab 9-2X Vehicles for Takata Air Bag Recall  
Safety Recalls 15044-01, 15045-01, and 15046-01  
Front Passenger Air Bag Inflator Replacement  
Revised Service Procedure section

Models: 2006 Saab 9-2X

To: All General Motors Dealers

These bulletins have been revised to provide updated information regarding the scan tool. Please discard all copies of 15044, 15045, and 15046.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS