

Subarunet Announcement



To: All Subaru Retailers
From: Subaru of America, Inc.
Date: October 10, 2018

UPDATE: Takata Recalls Front Passenger Air Bag Inflator Owner Renotifications

As we work through the Takata recall process, we will continue to mail owner re-notification letters to urge customers to schedule an appointment for the repair. This notification process is being prioritized in phases, based on parts supply, age of the inflator in the vehicle (oldest first), and geographic registration history of the vehicle.

The next group of renotification letters will include the following affected vehicles, based on recently refreshed owner information from IHS (Polk):

TKA16:

- 2011 Forester
- 2010-2011 Impreza and WRX
- 2009 Legacy and Outback
- 2006-2011 Tribeca

TKB16:

- 2006-2008 Impreza and WRX
- 2006-2008 Tribeca

TKA17:

- 2009 Legacy and Outback
- 2006-2011 Impreza
- 2006-2012 WRX
- 2006-2012 Tribeca

TKB17:

- 2009 Legacy and Outback
- 2006-2009 Tribeca

TKC17:

- 2006-2008 Tribeca

TKA18:

- 2009-2013 Forester
- 2009-2011 Impreza
- 2009-2013 WRX
- 2009-2013 Legacy and Outback
- 2009-2013 Tribeca

TKB18:

- 2009-2010 Forester
- 2009-2010 Impreza and WRX
- 2009-2010 Legacy and Outback
- 2009-2010 Tribeca

TKC18:

- 2009 Forester
- 2009 Impreza and WRX
- 2009 Legacy and Outback
- 2009 Tribeca

Approximately 154,000 renotifications will be mailed, nationally. Refreshed affected VIN lists will be distributed to each Region/Zone Office, which include the latest owner registration data for all open Takata recalls.

As always, please be sure to review the latest version of the Product Campaign Bulletin on STIS for the installation instructions and detailed parts information.

Thank you.