



**IMPORTANT SAFETY RECALL**

**AUTOCAR INDUSTRIES, LLC SAFETY RECALL ACTT-1701  
NHTSA RECALL NO. 17V-049  
March, 2017**

**TO:** U.S. and Canadian Distributors  
Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar Industries LLC, has decided that a defect that relates to motor vehicle safety exists in 2016-2017 model year Xspotter chassis. These chassis were manufactured between 14 July 2015 and 7 December 2016 with non-sequential serial numbers in the range 220716 and 223532. Accordingly, a recall to address this issue is being initiated effective 10 March 2017.

**MODELS  
AFFECTED:** Autocar Xspotter MY 2016-2017

**COMPONENTS  
AFFECTED:** Missing dimmer switch to adjust dash illumination.

**SAFETY DEFECTS  
AND POTENTIAL  
RISKS:** Without a switch to adjust the dash illumination brightness, the dash lights may be too dim or too bright with either condition increasing the risk of a crash.

**REPAIR  
REQUIRED:** A dimmer switch will be installed to adjust dash illumination. A safety recall bulletin with the repair and labor code will be available on 10 March, 2017.

**REPAIR  
AVAILABLE:** VIN profiles in the Autocar Warranty System will be updated to show the open recall on 10 March 2017.

**REMINDER:** It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department at [warranty@autocartruck.com](mailto:warranty@autocartruck.com).

Sincerely,

**AUTOCAR INDUSTRIES, LLC**

ACF 00002 Rev. 000