



IMPORTANT SAFETY RECALL

**AUTOCAR, LLC SAFETY RECALL ACX-1701
NHTSA RECALL NO. 17V-050
March, 2017**

TO: U.S. and Canadian Distributors
Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act.

Autocar, LLC, has decided that a defect that relates to motor vehicle safety exists in 2013-2016 model year Xpeditor chassis. These chassis were manufactured between 26 June 2012 and 5 November 2015 with non-sequential serial numbers in the range 214916 to 221453. Accordingly, a recall to address this issue is being initiated effective 17 March 2017.

MODELS Autocar Xpeditor MY 2013-2016
AFFECTED:

COMPONENTS S-cam brackets on the rear axle.
AFFECTED:

SAFETY DEFECTS If the brake assembly S-cam tube bolts loosen, the brakes could engage without
AND POTENTIAL warning, increasing the risk of a crash.
RISKS:

REPAIR The rear brake chambers will be changed from type 36/36 to 30/36 and the S-cam
REQUIRED: brackets and associated hardware will be replaced. A Safety Recall Bulletin with the
repair procedure and labor code will be available on 17 March 2017.

REPAIR VIN profiles in the Autocar Warranty System will be updated to show the open recall on
AVAILABLE: 17 March 2017.

REMINDER: It is a violation of Federal law to sell or lease a vehicle covered by this recall notice
unless the recall remedy has been completed. Substantial civil penalties apply to
violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department
at warranty@autocartruck.com.

Sincerely,

AUTOCAR, LLC

ACF 00002 Rev. 000