



REV Recreation Group
P.O. Box 1007
Decatur, IN 46733
(800) 509-3417

IMPORTANT RECALL INFORMATION #170301REV

April 2017

**TO: ALL REV RECREATION GROUP DEALER PRINCIPALS,
SERVICE MANAGERS AND PARTS MANAGERS**

**SUBJECT: RECALL CAMPAIGN #170301REV
Securing the Onan EFI 5.5 Kw Generator's External Fuel Pump
and In-Line Fuel Filter**

REV Recreation Group, Inc., on behalf of its manufacturing center located in Decatur, Indiana, is requesting your assistance in conducting a voluntary recall notification campaign in accordance with the United States National Traffic and Motor Vehicle Safety Act.

REV Recreation Group, Inc., has decided that a safety defect relating to motor vehicle safety exists in certain Holiday Rambler brand Class A gas motorhomes and certain Fleetwood brand class A gas motorhomes, manufactured between March 12, 2014 and February 22, 2017 and equipped with an Onan EFI 5.5 Kilowatt generator:

Holiday Rambler brand:

Model year 2017 Vacationer XE

Model year 2016-2017 Admiral XE (equipped with Option 331 Dual Air Conditioners and 5.5 Kw EFI Generator)

Fleetwood brand:

Model year 2015 Bounder Classic

Model year 2016-2017 Flair (equipped with Option 331 Dual Air Conditioners and 5.5 Kw EFI Generator)

Model year 2016 Storm (model 35SK)

Model year 2017 Storm

Model year 2015 Terra (models 31TS and 35K)

Model year 2015-2016 Terra (models 34B and 36 R)

We are notifying the owners of the affected units in order to correct the problem. A copy of the letter sent to owners of record is attached for your information.

WHAT IS THE PROBLEM?

On motor homes affected by this recall, the external fuel pump and inline fuel filter for the Onan 5.5 Kilowatt Generator may be improperly secured to the underside of the motorhome chassis. If the fuel pump, fuel filter, or connected fuel lines detach or are jarred loose, a fuel leak may result, posing the risk of fire or explosion in the presence of an ignition source.

WHAT SHOULD YOU DO?

Owners of the above mentioned motor homes have been asked to contact a REV Recreation Group dealer to have the described defect remedied. In the event that you are contacted by a customer, please verify eligibility by referring to the serial number range listed in the attached **Recall Service Bulletin #170301REV** prior to beginning repairs.

Once repairs have been completed according to **Recall Service Bulletin #170301REV**, have the customer sign your dealership's **Internal Repair Order**. Warranty labor claims are to be submitted electronically to REV Recreation Group. Customers will not be charged for these repairs.

If you have one of these vehicles in your inventory, you will be mailed a Safety Recall Notice for that specific motor home. REV Recreation Group dealers are required to make repairs to stock units on dealer lots prior to sale or lease.

Federal Law (Section 154 of the National Highway Traffic and Motor Vehicle Safety Act) of 1966 requires that: If you have received a notice of recall or failure to comply from REV Recreation Group, Inc., or any component manufacturer, you must repair or otherwise correct the defect on vehicles remaining in your inventory according to the notification before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

Please review this entire package with your parts and service staff to familiarize them with the step-by-step procedure and implement the Voluntary Recall Campaign.

Thank you for helping REV Recreation Group with its continuing efforts to maintain customer satisfaction. If you have any questions, please contact your REV Recreation Group Service Center.

Sincerely,

REV RECREATION GROUP, INC.

Attachments: Recall #170301REV Customer Letters
Recall #170301REV Service Bulletin