



REV Recreation Group
P.O. Box 1007
Decatur, IN 46733
(800) 509-3417

IMPORTANT RECALL INFORMATION #170317REV

APRIL 2017

**TO: ALL FLEETWOOD RV DEALER PRINCIPALS,
SERVICE MANAGERS
AND PARTS MANAGERS**

**SUBJECT: RECALL CAMPAIGN #170317REV
Federal Certification Label Replacement
Model Year 2017 Fleetwood Bounder, Model 35 P only**

REV Recreation Group, Inc., on behalf of its manufacturing center located in Decatur, Indiana, is requesting your assistance in conducting a voluntary recall notification campaign in accordance with the requirements of the United States National Traffic and Motor Vehicle Safety Act.

REV Recreation Group, Inc., has decided that the certification labels for certain model year 2017 Fleetwood Bounder Model 35 P Class A motorhomes are incorrect and must be replaced. These motorhomes were manufactured at our Decatur, Indiana plant November 18, 2016 through February 9, 2017. We are notifying the owners of the affected units in order to correct the problem. A copy of the letter sent to owners is attached for your information.

WHAT IS THE PROBLEM?

REV Recreation Group, Inc. has become aware that the tire size printed on the Certification Label is incorrect. The incorrect tire size is "235/80R 22.5 G"; the correct tire size is "255/80R 22.5 G". No other values printed on the label have been changed.

To correct this non-compliance, it is necessary to replace the Certification Label as described in the attached Recall Service Bulletin #170317REV.

WHAT SHOULD YOU DO?

If you have one of these vehicles in your inventory, you will be mailed a Recall Notice and replacement Federal Certification Label for that specific motorhome. REV Recreation Group dealers are required to make repairs to stock units on dealer lots prior to sale or lease.

Please check your motorhome inventory and perform the label replacement procedure on affected units as outlined in the attached Recall Service Bulletin #170317REV. It is imperative that this procedure is completed prior to the sale of the affected units so your customers will not be inconvenienced.

In the event that a customer contacts you to have the described non-compliance remedied, please verify eligibility by referring to the serial number range listed on the attached Recall Service Bulletin #170317REV prior to beginning the inspection and repairs.

Once repairs are completed, have the customer sign your dealership's Internal Repair Order and submit your labor claim electronically via the REV warranty portal. Customers will not be charged for these repairs.

Federal Law (Section 154 of the National Highway Traffic and Motor Vehicle Safety Act) of 1966 requires that: If you have received a notice of recall or failure to comply from Fleetwood RV or any component manufacturer, you must repair or otherwise correct the defect on vehicles remaining in your inventory according to the notification before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

Please review this entire package with your parts and service staff to familiarize them with the step-by-step procedure and implement the Voluntary Recall Campaign.

Thank you for helping REV Recreation Group with its continuing efforts to maintain customer satisfaction. If you have any questions, please contact REV Recreation Group Dealer Support.

Sincerely,

REV RECREATION GROUP, INC.

Attachments: Recall #170317REV Customer Letter
Recall #170317REV Service Bulletin