



Michael A. Berardi
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 28, 2017

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Advance Notice - Compliance Recall 17C05
Certain 2017 Model Year Edge Vehicles Equipped with Panoramic Vista Roof
Missing Front Windshield Header Welds

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Edge	2017	Oakville	February 21, 2017 through February 22, 2017

Affected vehicles are identified in OASIS and FSA VIN Lists.

NOTE: There are 84 total affected vehicles in the United States.

REASON FOR THIS COMPLIANCE RECALL

The affected vehicles may not conform to the requirements specified by Federal Motor Vehicle Safety Standard (FMVSS) No. 214 – Dynamic performance requirements for side impact crash. The front windshield headers may have been improperly welded and could be missing welds. Vehicles with an improperly welded windshield header may have reduced lateral structural integrity, potentially increasing the risk of injury in a side impact crash.

SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this compliance recall. A complete Dealer Bulletin will be released the week of April 24, 2017, when it is anticipated that parts ordering information and repair instructions will be available to support this compliance recall.

CUSTOMER NOTIFICATION

Owners of record will be notified via first-class mail the week of May 15, 2017, after repair instructions and parts ordering information have been provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$21,000 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

Michael A. Berardi