

Original Publication Date: June 29, 2017

To: All Toyota Dealer Principals, General Managers, Service Managers, and Parts Managers

Subject: **Safety Recall H0K – *Remedy Notice***
Certain 2016 Model Year Toyota Tundra vehicles
Incorrect Passenger Side Knee Airbag Fasteners

Background:

On June 29, 2017, Toyota filed a Defect Information Report (DIR) with the National Highway Traffic Safety Administration (NHTSA) reporting to the agency a voluntary Safety Recall on five 2016 Toyota Tundra vehicles.

As of June 29, 2017 the five vehicles involved in this Safety Recall have been identified and repaired during the course of our investigation of the issue. ***There is no action required by dealers.*** For reference, additional details regarding this Safety Recall are provided below.

Frequently Asked Questions**Q1: What is the condition?**

A1: During vehicle assembly, it is possible that incorrect bolts were used to install the front passenger knee airbag module. This may affect the performance of the knee airbag, increasing the risk of injury during a crash.

Q2: What is Toyota going to do?

A2: As of June 29, 2017 Toyota has already identified and repaired all vehicles involved in this Safety Recall.

Q3: Which and how many vehicles are covered by this Safety Recall?

A3: There are five 2016 Tundra vehicle covered by this Safety Recall.

Model Name	Model Year	Production Period
Tundra	2016	May 27, 2016

Q3a: Are there any other Lexus/Toyota/Scion vehicles covered by this Safety Recall in the U.S.?

A3a: No, there are no other Lexus/Toyota/Scion vehicles covered by this Safety Recall.

Thank you for your cooperation.
TOYOTA MOTOR SALES, U.S.A., INC.