

[Next Unread Message](#)[View Message](#)

<b>Sent on</b>	10	25	2017	<b>Expires on</b>	11	03	2017
<b>From</b>	Parts Operations						
<b>Subject</b>	Safety Recall: 2013-16 Accord BMS - Adhesive Update						

On Friday June 30, 2017, American Honda Motor Co., Inc. notified NHTSA and all Honda dealers of a **Stop Sale** and **Safety Recall** on certain 2013-16 Accord vehicles due to corrosion in some of the Battery Management Sensors (BMS). Two service bulletins support this action, the interim repair bulletin 17-057 and final remedy bulletin 17-069.

**Previously shared on 10/13/17:**

**Updates:**

- Effective Friday 10/27/17, Konishi bond will no longer be available for dealer ordering.
- Dealers should manage Konishi Bond stock accordingly between now and 10/27/17.
- Please remember each tube should repair approximately 60 vehicles and the part is non-returnable.
- Effective Tuesday 10/31/17:
  - Both S/B 17-057 and S/B 17-069 will be updated. Only replacement of battery sensors will be accepted.
  - Battery sensors will be available for dealer ordering. Please continue to make requests to Dealer Analysts for battery sensors up until 10/31.
- Additional Information:
  - Customer letters are expected to be mailed starting in November.
  - Additional iN message will be sent prior to 10/31/17 reminding dealers to manage inventory levels of Konishi Bond to prevent part obsolescence.

Thank you,

Parts Campaign Group  
American Honda Parts Operations

NG/ms