

## View Message

<b>Sent on</b>	11	07	2017	<b>Expires on</b>	12	01	2017
----------------	----	----	------	-------------------	----	----	------

<b>From</b>	Motorcycle National Field Service
-------------	-----------------------------------

<b>Subject</b>	Service Bulletin: 2017 CBR1000RR/RA/S1/S2 Fuel Cap Replacement
----------------	--

The Service Bulletin in support of the SAFETY and EMISSION RECALL for model year 2017 CBR1000RR/RA/S1/S2 motorcycles to replace the fuel cap assembly is posted on *iN*.

SERVICE BULLETIN [Service Bulletin CBR1000RR #9](#) includes the affected models, parts information, warranty claim information, and the repair procedure.

## PARTS INFORMATION

Important: *All remedy parts are VIN specific so that the remedy fuel cap matches the original equipment lock-set. Therefore, you must match the remedy parts kit to the motorcycle VIN before installation.*

Dealer Inventory: AHM will allocate all remedy parts for dealer-owned units to your dealership.

Customer Units: Contact TechLine with the motorcycle VIN to order remedy parts.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact Motorcycle TechLine through *TechLine Connect* on *iN*, or call TechLine at (800) 421-1900, option 9; or contact your District Service Manager.

Sincerely,  
American Honda Motor Co., Inc.  
Motorcycle Division

Bulletin #: 17-0315