




A **PACCAR** COMPANY

Kenworth Truck Company
P.O. Box 1000
Kirkland, Washington 98083-1000
(425) 828-5000

April 14, 2017

IMPORTANT SAFETY RECALL

Subject: Safety Recall 17KWA – Fuel Tee Fitting Leaking
NHTSA Recall number 17V-103
The VINs are listed on the back of this letter



Dear Kenworth Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company has decided that a defect, which relates to motor vehicle safety, exists in certain model K270/K370, T680, and T880 vehicles manufactured from November 18, 2014 through January 18, 2017. The vehicles may have been built with a defective fuel tee fitting that leaks. A manufacturing process control for the fuel tee was out of specification, which may have allowed the part to become porous, allowing a fuel leak during operation.

Fuel leakage in the presence of an ignition source could result in a fire.

<i>The problem is...</i>	A defective fuel tee.
<i>What your dealer will do...</i>	Replace the fuel tee fitting free of charge.
<i>What you must do ...</i>	Contact your Kenworth Dealer to schedule an appointment for repair.

Kenworth has initiated a recall to remedy the defect. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. This repair should take approximately **1.0 hour** of labor, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall, or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Customer Service Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.


We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Thank you,

Shondip Chakravarty
Director of Customer Service
Kenworth Truck Company

(Over Please)

Affected VINS:





A **PACCAR** COMPANY

Kenworth Truck Company
P.O. Box 1000
Kirkland, Washington 98083-1000
(425) 828-5000

April 14, 2017

IMPORTANT SAFETY RECALL

Subject: Safety Recall 17KWA – Fuel Tee Fitting Leaking
NHTSA Recall number 17V-103
The VINs are listed on the back of this letter



Dear Kenworth Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company has decided that a defect, which relates to motor vehicle safety, exists in certain model K270/K370, T680, and T880 vehicles manufactured from November 18, 2014 through January 18, 2017. The vehicles may have been built with a defective fuel tee fitting that leaks. A manufacturing process control for the fuel tee was out of specification, which may have allowed the part to become porous, allowing a fuel leak during operation.

Fuel leakage in the presence of an ignition source could result in a fire.

<i>The problem is...</i>	A defective fuel tee.
<i>What your dealer will do...</i>	Replace the fuel tee fitting free of charge.
<i>What you must do ...</i>	Contact your Kenworth Dealer to schedule an appointment for repair.

Kenworth has initiated a recall to remedy the defect. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. This repair should take approximately **1.0 hour** of labor, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall, or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Customer Service Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.


We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Thank you,

Shondip Chakravarty
Director of Customer Service
Kenworth Truck Company

(Over Please)

Affected VINS:






A **PACCAR** COMPANY

Kenworth Truck Company
P.O. Box 1000
Kirkland, Washington 98083-1000
(425) 828-5000

April 14, 2017

IMPORTANT SAFETY RECALL

Subject: Safety Recall 17KWA – Fuel Tee Fitting Leaking
NHTSA Recall number 17V-103
This notice applies to your vehicle; VIN: 1XKYD49X7JJ180544



Dear Kenworth Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company has decided that a defect, which relates to motor vehicle safety, exists in certain model K270/K370, T680, and T880 vehicles manufactured from November 18, 2014 through January 18, 2017. The vehicles may have been built with a defective fuel tee fitting that leaks. A manufacturing process control for the fuel tee was out of specification, which may have allowed the part to become porous, allowing a fuel leak during operation.

Fuel leakage in the presence of an ignition source could result in a fire.

The problem is...	A defective fuel tee.
What your dealer will do...	Replace the fuel tee fitting free of charge.
What you must do ...	Contact your Kenworth Dealer to schedule an appointment for repair.

Kenworth has initiated a recall to remedy the defect. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. This repair should take approximately **1.0 hour** of labor, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall, or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Customer Service Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Thank you,

Shondip Chakravarty
Director of Customer Service
Kenworth Truck Company



A **PACCAR** COMPANY

Kenworth Truck Company
P.O. Box 1000
Kirkland, Washington 98083-1000
(425) 828-5000

April 14, 2017

IMPORTANT SAFETY RECALL

Subject: Safety Recall 17KWA – Fuel Tee Fitting Leaking
NHTSA Recall number 17V-103
This notice applies to your vehicle; VIN: 1XKYD49X2JJ179804



Dear Kenworth Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company has decided that a defect, which relates to motor vehicle safety, exists in certain model K270/K370, T680, and T880 vehicles manufactured from November 18, 2014 through January 18, 2017. The vehicles may have been built with a defective fuel tee fitting that leaks. A manufacturing process control for the fuel tee was out of specification, which may have allowed the part to become porous, allowing a fuel leak during operation.

Fuel leakage in the presence of an ignition source could result in a fire.

The problem is...	A defective fuel tee.
What your dealer will do...	Replace the fuel tee fitting free of charge.
What you must do ...	Contact your Kenworth Dealer to schedule an appointment for repair.

Kenworth has initiated a recall to remedy the defect. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. This repair should take approximately **1.0 hour** of labor, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall, or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Customer Service Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Thank you,

Shondip Chakravarty
Director of Customer Service
Kenworth Truck Company

