Product Safety Recall

17085 Electric Power Steering Connector Cable Seal Not Seated



<u>GM</u>

IMPORTANT SAFETY RECALL

March 2017

This notice applies to your vehicle, VIN: ____

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2017 model year Buick LaCrosse vehicles. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

	 IMPORTANT Your vehicle is involved in GM safety recall 17085. Schedule an appointment with your GM dealer. This service will be performed for you at no charge. 		
Why is your vehicl being recalled?	Some of these vehicles have a condition in which the cable seal on one or both of the electric power steering (EPS) connectors may not be properly seated. If the seal is not properly seated on a connector, water could enter and corrode the connector, or create a high resistance condition capable of melting the connector, potentially resulting in a loss of EPS. If power steering assist is lost, manual steering functionality is retained but would require an increased steering effort, particularly at lower speeds, increasing the risk of a crash.		
What will we do?	Your GM dealer will verify the seals are fully seated and secure the seal to the affected connectors. This service will be performed for you at no charge . Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 20 minutes.		
What should you do?	You should contact your GM dealer to arrange a service appointment as soon as possible.		
Do you have questions?	If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.		
Г——	Division Number Toxt Telephones (TTV)		

Division	Number	Text Telephones (TTY)
Buick	1-866-608-8080	1-800-832-8425
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to http://www.safercar.gov. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 17V116.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Jeffrey M. Boyer Vice President Global Vehicle Safety