

IMPORTANT SAFETY RECALL

June 26, 2017

**This notice applies to your vehicle: WP1AB2A59FLF
NHTSA Recall Number: 17V133**

**Subject: Porsche Safety Recall AH02 – Replacing Occupant Detection System for
Front Passenger Seat**

**2015 - 2016 Macan S
2015 - 2016 Macan Turbo
2017 Macan GTS**

Dear

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Porsche has determined that a defect which relates to motor vehicle safety exists in certain model year 2015 – 2016 Macan S, 2015 – 2016 Macan Turbo, and 2017 Macan GTS vehicles. The sensor mat for the occupancy detection system may fail, leading to the possible failure to detect the presence of a front passenger. As a result, the front passenger airbag may not deploy in the event of a crash and, as such, may fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 208 "Occupant Crash Protection." However, in the event that the occupant detection mat malfunctions, the airbag warning lamp or "Passenger Airbag ON/OFF" lamp will show the status of the Airbag in order to alert occupants. Our records show that you are the owner of a vehicle affected by this action.

What is the issue?

Sensor mats for the occupant detection system, located in the front passenger seat cushion, contain a conductive fabric that can fracture.

If the activated airbag warning or "Passenger Airbag ON/OFF" lamps are not noticed by the driver or the front passenger, and the front seat passenger does not move to a different seating position or exit the vehicle, the protective benefit of the front airbag system will not be available to the front seat passenger in the event of a crash.

What will we do?

Porsche is conducting a safety recall and the affected components will be replaced. Vehicles affected by this action will be recalled to the workshop and an optimized sensor mat and seat cushion will be installed. Of course, these repairs will be completed at no charge to you.

What should you do?

Please make contact with your authorized Porsche dealership to schedule a repair appointment and to arrange in advance for a Porsche loaner vehicle should you require alternate transportation during repair period. Replacing the affected components are expected to take two hours to complete.

Lease vehicles and address change

If you are the lessor and registered owner of the vehicle identified in this action, the law requires you to forward this letter immediately via first-class mail to the lessee within ten days of receipt. If you have changed your address or sold the vehicle, please fill out the enclosed prepaid Owner Reply Card and mail it to us so we can update our records.

Reimbursement of Expenses

This recall will be carried out at no expense to the customer.

Can we assist you further?

If your authorized Porsche dealer fails or is unable to complete this work free of charge within a reasonable length of time, please call or write:

Porsche Cars North America, Inc.
Attn: Customer Commitment Department
One Porsche Drive
Atlanta, GA 30354
1-800-PORSCHE

If you still cannot obtain satisfaction, you may file a complaint with:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue, S.E.
Washington, D.C. 20590

or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.safercar.gov>.

We apologize for any inconvenience this matter may cause you. However, we are taking this action to help ensure your safety and continued satisfaction with your vehicle.

Very truly yours,



Tim Quinn
Vice President, After Sales

PORSCHE CARS NORTH AMERICA, INC.