

BMW



June 2017

Dear BMW Owner: VIN

At BMW of North America, we are committed to maintaining a level of automotive and service excellence that exceeds your expectations now and in the future.

We have become aware that the tire information label on your vehicle may contain incorrect information. Our records indicate that your vehicle is potentially affected.

The tire information label is visible upon opening the driver's door. The label has a white background and contains tire pressure and other tire related information. The label on potentially affected vehicles contains incorrect values for the tire size.

Please note that correct values are contained in the vehicle's Owner's Manual.

Enclosed with this letter is a new tire information label. Please contact an authorized BMW center to set up an appointment to have this new label properly installed on your vehicle. On the day of the appointment, please bring this label along with your vehicle to an authorized BMW center. The BMW center will replace the label on your vehicle free of charge, which should take approximately 15 minutes.



0000005
0000001

We sincerely apologize for your inconvenience.

We appreciate your confidence in our product, and we wish to do everything we can to retain your confidence. Should you need additional assistance, you may contact BMW Customer Relations and Services via Email at CustomerRelations@bmwusa.com or by calling 1-800-831-1117.

BMW recommends that you and your passengers wear your safety belt at all times.

Sincerely,

BMW of NORTH AMERICA, LLC

Company
BMW
of North America, LLC

BMW Group Company

Mailing Address
PO Box 1227
Westwood NJ 07675-
1227

Telephone
(800) 831-1117

Fax
(201) 930-8362

E-mail
CustomerRelations@
bmwusa.com

Internet
bmwusa.com