



ZOOM-ZOOM

IMPORTANT SAFETY RECALL

**2004 RX-8
Front Lower Arm Ball Joint - Safety Recall 1117E
NHTSA Campaign No. 17V-355**

September, 2017

This notice applies to your vehicle: VIN _____

Dear Mazda Owner:

In August, you received a notice that your vehicle was included in a recall involving the front lower arm ball joint case cracking due to an inappropriate manufacturing process on certain 2004 RX-8 vehicles produced from April 10, 2003 through May 7, 2004. Due to an error in processing the list of affected vehicles, some RX-8 vehicles produced after May 7, 2004 were mistakenly included in the recall and mailed this notification. Since your vehicle was produced after May 7, 2004 and already has the correct lower arm ball joints, it is not subject to recall 1117E and does not require the 1117E recall repair.

Important Note:

Your vehicle is still subject to recall 1017E (NHTSA Campaign Nos. 17V-354 and 16V-793) - Fuel Leak at Fuel Pump Discharge Pipe and Fuel Leak at Fuel Pump Rings. We strongly encourage you to contact your authorized Mazda dealer to make an appointment to repair concerns from recall 1017E if you have not done so already.

We sincerely apologize for any confusion or inconvenience this error may have caused you.

Still have questions?

If you have any questions regarding this situation, please contact our Customer Experience Center toll free at (800) 222-5500, select option #6.

Sincerely,

Mazda North American Operations