

Representative Letter – Customer letters are brand, model and model year specific; listing the 17-digit VIN and are personalized.



IMPORTANT SAFETY RECALL

August 2017

This notice applies to your vehicle, **VIN:** _____

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2014-2017 model year Buick Encore, Chevrolet Corvette, Silverado LD, GMC Sierra LD vehicles, 2014-2016 model year Buick Lacrosse, Chevrolet Caprice Police, Spark EV, SS vehicles, 2015-2016 model year Cadillac Escalade, Escalade ESV, Chevrolet Silverado HD, Trax vehicles, 2015-2017 model year Chevrolet Suburban, Tahoe, GMC Sierra HD, Yukon, Yukon XL vehicles. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- Your vehicle is involved in GM safety recall 17287.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

Why is your vehicle being recalled?

In receiving service for the condition covered by GM recall number 16V-651 (16007), your vehicle did not receive the new sensing and diagnostic module (SDM) software that is necessary to remedy the recall condition. The original SDM software in your vehicle, which controls airbag and pretensioner deployment, contains a defect which may prevent the deployment of frontal airbags and pretensioners in certain rare circumstances. If the frontal airbags and seatbelt pretensioners do not deploy when required, there is an increased risk of injury to occupants in a crash.

What will we do?

Your GM dealer will reprogram the SDM with new software that eliminates this defect using a revised service procedure. In vehicles with any previous deployment events recorded in the SDM, the dealers will replace the existing SDM with a new SDM containing the latest software. This service will be performed for you at no charge. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 20 minutes up to two hours.

What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible.

Did you already pay for this repair?

Even though you may have already had repairs for this condition, you will still need to take your vehicle to your dealer for additional repairs. If you have paid for repairs for the recall condition, please complete the enclosed reimbursement form and present it to your dealer with all required documents. Working with your dealer will expedite your request, however, if this is not convenient, you may mail the completed reimbursement form and all required documents to Reimbursement Department, PO Box 33170, Detroit, MI 48232-5170. The completed form and required documents must be presented to your dealer or received by the Reimbursement Department by July 31, 2018, unless state law specifies a longer reimbursement period.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Buick	1-866-608-8080	1-800-832-8425
Cadillac	1-866-982-2339	1-800-833-2622
Chevrolet	1-800-630-2438	1-800-833-2438
GMC	1-866-996-9463	1-800-462-8583
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 17V437.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Jeffrey M. Boyer
Vice President
Global Vehicle Safety

Enclosure
GM Recall 17287