



**PETERBILT MOTORS COMPANY**  
A **PACCAR** COMPANY  
1700 WOODBROOK STREET  
DENTON, TEXAS 76205-7864  
940-591-4000

**IMPORTANT SAFETY RECALL INFORMATION**



U.S. Department of  
Transportation

Issued in Accordance  
With Federal Law



SANFORD S SERVICE CENTER, INC.  
PO BOX 1321  
PAHOA, HI 96778-1321

0001



357213-717-B

Recall Notice: 717-B

**RECALL NOTICE**

September 18, 2017

This notice applies to your vehicle. VINs are listed below or on the back of this page.

Subject: Safety Recall 717-B Cab Fuse Block Fires  
NHTSA 17V-471  
EXPIRATION DATE: NONE

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors Company has decided that a defect which relates to motor vehicle safety exists in certain Model 567 and 579 vehicles manufactured between July 13, 2012 and December 14, 2016 and that were equipped with spotlights. The spotlight circuit may not be adequately protected in the event of a short, which could increase the risk of fire causing injury and/or damage to property.

<b>The problem is ...</b>	A fire may occur if the spotlight circuit shorts out
<b>Correction ...</b>	Remove and replace the optional polyfuse circuit breaker with a standard fuse
<b>What you must do ...</b>	Contact your Peterbilt dealer immediately to schedule an appointment

Peterbilt has initiated a recall to remedy the defect. Please contact a Peterbilt dealership to schedule this repair. To find your nearest Peterbilt dealer, please visit Dealer Locator at [www.Peterbilt.com](http://www.Peterbilt.com). This repair should take approximately **0.3 hours** labor depending on configuration and dealer scheduling. This repair will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St. Denton, TX 76205, Attn: Quality Services Department, phone 940-591-4220.


If you conclude that Peterbilt has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We apologize for any inconvenience this preventive procedure may cause and thank you for your participation in helping Peterbilt provide the highest levels of customer satisfaction and service expertise.

We value your business and appreciate your ongoing loyalty to Peterbilt and its dealer network. Industry-leading quality, performance and reliability are hallmarks of Peterbilt products, and we thank you for making Peterbilt your truck of choice.

Sincerely,



Doug Gunter  
Director of Warranty  
Peterbilt Motors Company

Our records indicate that these vehicles are affected by 717-B and are owned by **SANFORD S SERVICE CENTER, INC.**

1NPCX4TX6HD444117

1NPCX4TX7GD357213