



Ford Motor Company
Ford Customer Service Division
P. O. Box 1904
Dearborn, Michigan 48121-1904



771040909497

868/000290/0002



R. FILE
330 TOWN CENTER DR
STE 500
DEARBORN, MI 48126-2796

December 2017

***** IMPORTANT SAFETY RECALL *****
(PROGRAMA DE SEGURIDAD IMPORTANTE)

Safety Recall Notice 17S36 / NHTSA Recall 17V-671
Aviso de Revisión de Seguridad 17S36

2017 F-150 Ford Truck

Your Vehicle Identification Number (VIN):

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in your vehicle, with the VIN shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

What is the issue?


On your vehicle, it may be possible the roll pin attaching the transmission shift linkage to the transmission may come out. If this happens, movement of the shift lever by the driver will not change the transmission gear state.

What is the risk?

The driver may experience the following:

- Unintended vehicle movement if the parking brake is not applied, increasing the risk of a crash or injury
- When exiting the vehicle, if the transmission is not in Park, the ignition key can be removed, but a warning chime and message will be displayed in the instrument cluster indicating Transmission Not in Park (as shown to left)
- If the vehicle is equipped with a console shifter, the shifter indicator could display conflicting gear position with the instrument cluster PRNDM indicator
- No ability to restart the vehicle, unless the roll pin came out when the transmission was in Park or Neutral
- A loose or low effort feel of the shift lever (regardless of transmission gear position when the pin falls out)

These conditions increase the risk of a crash or injury.



Instrument Cluster Message

What will Ford and your dealer do?

Ford Motor Company has authorized your dealer to replace the transmission roll pin free of charge (parts and labor).

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time. Additional time may be required to allow the engine to cool prior to performing this repair.

What should you do?

When operating your vehicle prior to repair, please make sure the parking brake is applied whenever the vehicle is parked.

Please call your dealer without delay to schedule a service appointment for Recall 17S36. Provide the dealer with your VIN, which is printed near your name at the beginning of this letter.

If you do not already have a servicing dealer, you can access www.Fordowner.com for dealer addresses, maps, and driving instructions. Ford Motor Company wants you to have this safety recall completed on your vehicle. The vehicle owner is responsible for making arrangements to have the work completed. Ford Motor Company can deny coverage for any vehicle damage that may result from the failure to have this recall performed on a timely basis. Therefore, please have this recall performed as soon as possible.

Please note: Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

NOTE: You can receive information about Recalls and Customer Satisfaction Programs through our FordPass App. The app can be downloaded through the App Store or Google Play. In addition there are other features such as reserving and paying for parking in certain locations and controlling certain functions on your vehicle (lock or unlock doors, remote start) if it is equipped to allow control.

What if you no longer own this vehicle?

If you no longer own this vehicle, and have an address for the current owner, please forward this letter to the new owner.

You received this notice because government regulations require that notification be sent to the last known owner of record. Our records are based primarily on state registration and title data, which indicate that you are the current owner.

Can we assist you further?

If you have difficulties getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance.

RETAIL OWNERS: If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332** and one of our representatives will be happy to assist you. If you wish to contact us through the Internet, our address is: www.Fordowner.com.

For the hearing impaired call 1-800-232-5952 (TDD). Representatives are available Monday through Friday: 8:00AM - 8:00PM (Eastern Time).

FLEET OWNERS: If you have questions or concerns, please contact our **Fleet Customer Information Center at 1-800-34-FLEET**, choose Option #3, and one of our representatives will be happy to assist you. If you wish to contact us through the Internet, our address is: www.fleet.ford.com.

**Can we assist you
further?
(Continued)**

Representatives are available Monday through Friday: 8:00AM - 8:00PM (Eastern Time).

If you are still having difficulty getting your vehicle repaired in a reasonable time or without charge, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to www.safercar.gov. Reference NHTSA Safety Recall 17V-671.

**Para asistencia en
Español**

Visite nuestro sitio web para ver este anuncio en Español al siguiente dirección: <https://es.owner.ford.com/recall>.

Si necesita ayuda o tiene alguna pregunta, por favor llame al Centro de Relación con Clientes al 1-866-436-7332 y presione 2 para Español.

Thank you for your attention to this important matter.

Ford Customer Service Division