



REV GROUP

## **IMPORTANT SAFETY RECALL NHTSA Recall No. 17V-685**

This notice applies to your vehicle, please see attached VIN list.

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

November 30, 2017

PACE Suburban Bus  
405 Taft Drive  
South Holland, IL. 60473

Attn: Larry Braun

**Subject: Safety Recall Notice  
NHTSA Recall No. 17V-685**

### **Reason for This Recall**

Eldorado National California, Inc. ("Eldorado") has decided that a defect which relates to motor vehicle safety exists in the Seat Belts of certain Recaro Commercial Bus Driver Seats, Part Shipments, and Service Kits sold or provided under warranty between December 20, 2016 and August 22, 2017. The affected seat belts experience a "pre-locked buckle" condition that prevents the operator from physically latching the belt. This may lead some drivers to operate the vehicle without the seat belt secured, increasing the risk of injury in the event of a crash.

Certain Recaro Commercial Bus Driver Seats experience a "prelocked buckle" condition where an internal mechanism in the buckle becomes stuck in the locked position. This condition prevents the seat belt Latch-Plate (tongue) from being inserted into the buckle. As a result, the driver's seat belt buckle on any bus with a VIN listed in this letter will need to be inspected and replaced if the Julian code on the back of the buckle is within the date range of the recall.


## **What We Are Asking You To Do**

Please locate all Recaro drivers seats in your Eldorado buses, part shipments, and service kits delivered under the orders referenced in the attached list. Remember to search any existing vehicles, vehicles that may have had the replacement seats or seat belt parts installed, as well as your parts inventory.

Inspect the Julian code on the back of the driver's seat belt buckle for all possibly affected parts (See table and figure below).

<b>Buckles with Julian codes within these ranges are part of the recall:</b>	
<b>Julian Codes:</b>	<b>16335 to 16365 (=Dec. 1st 2016 to Dec. 31st 2016)</b>
	<b>17001 to 17178 (= Jan. 1st 2017 to June 27th 2017)</b>

**Back of Seat belt buckle**



### **For loose buckles not currently installed on a seat:**

- For loose buckles that are possible subject to the recall, please inspect the buckles and contact Recaro to arrange for any recalled units to be returned to them at no cost to you: Contact: Robert Mendoza [Robert.Mendoza@eldorado-ca.com](mailto:Robert.Mendoza@eldorado-ca.com) 909-591-9557
- Eldorado will ship you replacement units for all recalled buckles at no cost.
- Eldorado will credit your account or send you a check for the inspections and or replacement labor. Reimbursement will be: Inspection 5 minutes based on \$60 per hour. Additional replacement 20 minutes based on \$60 per hour.
- All defective buckles will need to be returned to Eldorado to qualify for credit. Eldorado will supply a UPS # to have all buckles returned to them at no cost to you.

### **For buckles currently installed on a seat:**

- For buckles currently installed on a seat that are possible subject to the recall, please inspect the buckles and record the results on the attached Inspection Sheet, including Seat Serial #, Bus Serial # (which is the of VIN number) and whether or not the buckle was in the recall code range. The Seat Serial # can be viewed by sliding the seat all the way forward and inspecting the white 4X1 sticker located on the top rear plate of the suspension. (See figure below.)



- Submit the completed inspection sheet to Recaro at the following email address: Robert Mendoza [Robert.Mendoza@eldorado-ca.com](mailto:Robert.Mendoza@eldorado-ca.com) 909-591-9557
- Eldorado will ship you new replacement parts for all recalled buckles along with detailed re-work instructions.
- Replace the recalled seat belt buckles per Recaro's instructions.
- All defective buckles will need to be returned to Eldorado to qualify for credit. Eldorado will supply a UPS # to have all buckles returned to them at no cost to you.
- Eldorado will credit your account or send you a check for the inspections and or replacement labor. Reimbursement will be: Inspection 5 minutes based on \$60 per hour. Additional replacement 20 minutes based on \$60 per hour.
- If you have already performed this repair, you are eligible to receive reimbursement for the cost of performing the pre-notification repair of the problem that is the subject of this recall.

## **What EIDorado Will Do**

EIDorado will work with the seating supplier (Adient-Recaro) to complete the recall fix at no cost to you and will reimburse you for all labor necessary to perform the fix. At your option, EIDorado personnel are available to perform the recall repair at no cost to you.

## **If You Have Concerns:**

Any questions regarding the information should be directed to:

Robert Mendoza [Robert.Mendoza@eldorado-ca.com](mailto:Robert.Mendoza@eldorado-ca.com) Phone # 909-591-9557

or

Ken Edwards [Ken.Edwards@eldorado-ca.com](mailto:Ken.Edwards@eldorado-ca.com) Phone # 909-591-9557

## **What if you no longer own this vehicle?**

If you are not the current owner of the vehicle, please indicate this in a response to EIDorado.

## **Notifications**

If you have experienced this specific condition and have already paid to have it remedied, you may be eligible for reimbursement. Please mail your original receipt and proof of payment to the above address for reimbursement consideration.

Should EIDorado fail or be unable to correct the defect without charge and within a reasonable amount of time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to lessee within 10 days.

We are sorry to cause this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our buses.

Sincerely,



Tony Wayne

Vice President & General Manager  
EIDorado National California, Inc.

VINs covered under this recall are on attached sheet.

	A	B	C	D	E	F	G	H	I	J
	WO #	vin			ship date	ship to name	ship to address	ship to city	ship st	ship zip
1	561964	1N9MNAAC61HC084154	EZ Rider	EZRM-32	5/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
2	561965	1N9MNAAC63HC084155	EZ Rider	EZRM-32	5/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
3	561966	1N9MNAAC65HC084156	EZ Rider	EZRM-32	5/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
4	561967	1N9MNAAC67HC084157	EZ Rider	EZRM-32	5/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
5	561968	1N9MNAAC69HC084158	EZ Rider	EZRM-32	6/24/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
6	561969	1N9MNAAC60HC084159	EZ Rider	EZRM-32	8/3/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
7	561970	1N9MNAAC67HC084160	EZ Rider	EZRM-32	6/24/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
8	401153	1N9APALGXHC084112	AXESS	LF-40	3/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
9	401154	1N9APALGXHC084113	AXESS	LF-40	3/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
10	401155	1N9APALGXHC084114	AXESS	LF-40	3/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
11	401156	1N9APALGXHC084115	AXESS	LF-40	3/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
12	401157	1N9APALGXHC084116	AXESS	LF-40	4/11/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
13	401158	1N9APALGXHC084117	AXESS	LF-40	3/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
14	401159	1N9APALGXHC084118	AXESS	LF-40	3/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
15	401160	1N9APALGXHC084119	AXESS	LF-40	3/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
16	401161	1N9APALGXHC084120	AXESS	LF-40	4/18/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
17	401162	1N9APALGXHC084121	AXESS	LF-40	4/20/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
18	401163	1N9APALGXHC084122	AXESS	LF-40	4/18/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
19	401164	1N9APALGXHC084123	AXESS	LF-40	4/17/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
20	401165	1N9APALGXHC084124	AXESS	LF-40	4/18/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
21	401166	1N9APALGXHC084125	AXESS	LF-40	4/18/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
22	401167	1N9APALGXHC084126	AXESS	LF-40	4/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
23	401168	1N9APALGXHC084127	AXESS	LF-40	4/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
24	401169	1N9APALGXHC084128	AXESS	LF-40	4/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
25	401170	1N9APALGXHC084129	AXESS	LF-40	4/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
26	401171	1N9APALGXHC084130	AXESS	LF-40	4/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
27	401172	1N9APALGXHC084131	AXESS	LF-40	4/22/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
28	401173	1N9APALGXHC084132	AXESS	LF-40	4/22/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
29	401174	1N9APALGXHC084133	AXESS	LF-40	4/22/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
30	401175	1N9APALGXHC084134	AXESS	LF-40	4/22/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
31	401176	1N9APALGXHC084135	AXESS	LF-40	4/22/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
32	401177	1N9APALGXHC084136	AXESS	LF-40	5/12/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473

	A	B	C	D	E	F	G	H	I	J
34	401178	IN9APALG4HC084137	AXESS	LF-40	5/12/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
35	401179	IN9APALG6HC084138	AXESS	LF-40	5/18/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
36	401180	IN9APALG8HC084139	AXESS	LF-40	5/17/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
37	401181	IN9AP9N2HC084269	AXESS	LF-40	invoiced	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
38	401182	IN9APALG5HC084227	AXESS	LF-40	7/11/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
39	401183	IN9APALG7HC084228	AXESS	LF-40	7/13/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
40	401184	IN9APALG9HC084229	AXESS	LF-40	7/13/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
41	401185	IN9APALG5HC084230	AXESS	LF-40	7/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
42	401186	IN9APALG7HC084231	AXESS	LF-40	7/19/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
43	401187	IN9APALG9HC084232	AXESS	LF-40	7/19/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
44	401188	IN9APALG0HC084233	AXESS	LF-40	7/19/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
45	401189	IN9APALG2HC084234	AXESS	LF-40	invoiced	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
46	401190	IN9APALG4HC084235	AXESS	LF-40	7/19/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
47	401191	IN9APALG6HC084236	AXESS	LF-40	7/20/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
48	401192	IN9APALG8HC084237	AXESS	LF-40	7/20/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
49	401193	IN9APALGXHC084238	AXESS	LF-40	7/20/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
50	401194	IN9APALG1HC084239	AXESS	LF-40	7/20/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
51	401195	IN9APALG8HC084240	AXESS	LF-40	invoiced	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
52	401196	IN9APALGXHC084241	AXESS	LF-40	invoiced	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
53	401197	IN9APALG1HC084242	AXESS	LF-40	8/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
54	401198	IN9APALG3HC084243	AXESS	LF-40	8/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
55	401199	IN9APALG5HC084244	AXESS	LF-40	invoiced	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
56	401200	IN9APALG7HC084245	AXESS	LF-40	8/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
57	401201	IN9APALG9HC084246	AXESS	LF-40	8/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
58	401202	IN9APALG0HC084247	AXESS	LF-40	8/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
59	401203	IN9APALG2HC084248	AXESS	LF-40	8/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
60	401204	IN9APALG4HC084249	AXESS	LF-40	8/25/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
61	401205	IN9APALG0HC084250	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
62	401206	IN9APALG2HC084251	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
63	401207	IN9APALG4HC084252	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
64	401208	IN9APALG6HC084253	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
65	401209	IN9APALG8HC084254	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
66	401210	IN9APALGXHC084255	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473

	A	B	C	D	E	F	G	H	I	J
67	401211	1N9APALG1HC084256	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
68	401212	1N9APALG3HC084257	AXESS	LF-40	9/1/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
69	401213	1N9APALG5HC084258	AXESS	LF-40	9/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
70	401214	1N9APALG7HC084259	AXESS	LF-40	9/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
71	401215	1N9APALG3HC084260	AXESS	LF-40	9/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
72	401216	1N9APALG5HC084261	AXESS	LF-40	9/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
73	401217	1N9APALG7HC084262	AXESS	LF-40	9/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
74	401218	1N9APALG9HC084263	AXESS	LF-40	9/15/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
75	401219	1N9APALG0HC084264	AXESS	LF-40	9/16/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
76	401220	1N9APALG2HC084265	AXESS	LF-40	9/16/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
77	401221	1N9APALG4HC084266	AXESS	LF-40	9/20/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
78	401222	1N9APALG6HC084267	AXESS	LF-40	9/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
79	401223	1N9APALG8HC084268	AXESS	LF-40	9/22/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
80	401505	1N9APACL3HC084271	AXESS	LF-40	8/11/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
81	401506	1N9APACL3HC084272	AXESS	LF-40	8/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
82	401507	1N9APACL5HC084273	AXESS	LF-40	8/16/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
83	401508	1N9APACL7HC084274	AXESS	LF-40	8/16/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
84	401509	1N9APACL9HC084275	AXESS	LF-40	8/17/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
85	401510	1N9APACL0HC084276	AXESS	LF-40	8/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
86	401511	1N9APACL2HC084277	AXESS	LF-40	8/23/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
87	401512	1N9APACL4HC084278	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
88	401513	1N9APACL6HC084279	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
89	401514	1N9APACL2HC084280	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
90	401515	1N9APACL4HC084281	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
91	401516	1N9APACL6HC084282	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
92	401517	1N9APACL8HC084283	AXESS	LF-40	8/26/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
93	401518	1N9APACLXHC084284	AXESS	LF-40	9/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
94	401519	1N9APACL1HC084285	AXESS	LF-40	9/15/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
95	401520	1N9APACL3HC084286	AXESS	LF-40	9/15/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
96	401521	1N9APACL5HC084287	AXESS	LF-40	9/16/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
97	401522	1N9APACL7HC084288	AXESS	LF-40	9/16/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
98	401523	1N9APACL9HC084289	AXESS	LF-40	9/16/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
99	401524	1N9APACL5HC084290	AXESS	LF-40	9/16/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473

	A	B	C	D	E	F	G	H	I	J
100	401525	IN9APACL7HC084291	AXESS	LF-40	9/20/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
101	401526	IN9APACL9HC084292	AXESS	LF-40	9/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
102	401527	IN9APACL0HC084293	AXESS	LF-40	9/22/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
103	401528	IN9APACL2HC084294	AXESS	LF-40	9/22/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
104	401529	IN9APACL4HC084295	AXESS	LF-40	9/22/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
105	401530	IN9APACL6HC084296	AXESS	LF-40	9/23/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
106	401531	IN9APACL8HC084297	AXESS	LF-40	9/22/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
107	401532	IN9APACLXHC084298	AXESS	LF-40	9/23/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
108	401533	IN9APACL1HC084299	AXESS	LF-40	9/23/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
109	401534	IN9APACL4HC084300	AXESS	LF-40	9/23/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
110	401535	IN9APACL6HC084301	AXESS	LF-40	10/2/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
111	401536	IN9APACL8HC084302	AXESS	LF-40	10/2/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
112	401537	IN9APACLXHC084303	AXESS	LF-40	10/4/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
113	401538	IN9APACL1HC084304	AXESS	LF-40	10/2/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
114	401539	IN9APACL3HC084305	AXESS	LF-40	10/2/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
115	401540	IN9APACL5HC084306	AXESS	LF-40	10/6/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
116	401541	IN9APACL7HC084307	AXESS	LF-40	10/4/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
117	401542	IN9APACL9HC084308	AXESS	LF-40	10/4/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
118	401543	IN9APACL0HC084309	AXESS	LF-40	10/5/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
119	401544	IN9APACL7HC084310	AXESS	LF-40	10/12/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
120	401545	IN9APACL9HC084311	AXESS	LF-40	10/10/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
121	401546	IN9APACL0HC084312	AXESS	LF-40	10/10/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
122	401547	IN9APACL2HC084313	AXESS	LF-40	10/13/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
123	401548	IN9APACL4HC084314	AXESS	LF-40	10/13/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
124	401549	IN9APACL6HC084315	AXESS	LF-40	10/13/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
125	401550	IN9APACL8HC084316	AXESS	LF-40	10/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
126	401551	IN9APACLXHC084317	AXESS	LF-40	10/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
127	401552	IN9APACL1HC084318	AXESS	LF-40	10/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
128	401553	IN9APACL3HC084319	AXESS	LF-40	10/14/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
129	401554	IN9APACLXHC084320	AXESS	LF-40	10/18/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
130	401555	IN9APACL1HC084321	AXESS	LF-40	10/17/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
131	401556	IN9APACL3HC084322	AXESS	LF-40	10/17/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
132	401557	IN9APACL5HC084323	AXESS	LF-40	10/20/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473



	A	B	C	D	E	F	G	H	I	J
133	401558	1N9APACL8JC084001	AXESS	LF-40	10/19/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
134	401559	1N9APACLXC084002	AXESS	LF-40	10/20/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
135	401560	1N9APACL1JC084003	AXESS	LF-40	10/19/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
136	401561	1N9APACL3JC084004	AXESS	LF-40	10/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
137	401562	1N9APACL5JC084005	AXESS	LF-40	10/20/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
138	401563	1N9APACL7JC084006	AXESS	LF-40	10/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
139	401564	1N9APACL9JC084007	AXESS	LF-40	10/21/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
140	401565	1N9APACL0JC084008	AXESS	LF-40	10/24/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
141	401566	1N9APACL2JC084009	AXESS	LF-40	10/24/2017	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
142	401567	1N9APACL9JC084010	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
143	401568	1N9APACL0JC084011	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
144	401569	1N9APACL2JC084012	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
145	401570	1N9APACL4JC084013	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
146	401571	1N9APACL6JC084014	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
147	401572	1N9APACL8JC084015	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
148	401573	1N9APACLXC084016	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
149	401574	1N9APACL1JC084017	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
150	401575	1N9APACL3JC084018	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
151	401576	1N9APACL5JC084019	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
152	401577	1N9APACL1JC084020	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
153	401578	1N9APACL3JC084021	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
154	401579	1N9APACL5JC084022	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
155	401580	1N9APACL7JC084023	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
156	401581	1N9APACL9JC084024	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
157	401582	1N9APACL0JC084025	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
158	401583	1N9APACL2JC084026	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
159	401584	1N9APACL4JC084027	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
160	401585	1N9APACL6JC084028	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
161	401586	1N9APACL8JC084029	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
162	401587	1N9APACL4JC084030	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
163	401588	1N9APACL6JC084031	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
164	401589	1N9APACL8JC084032	AXESS	LF-40		PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473
165	401590	1N9APACLXHC084270	AXESS	LF-40	invoiced	PAGE-SOUTH HOLLAND DIVISION	405 TAFT DRIVE	SOUTH HOLLAND	IL	60473