

## Furrion cook top LP line

### Description

On certain Toy Hauler fifth wheel trailers manufactured with a Furrion cook top. The LP hose might be pushing against the oven causing stress on the LP hose connector at the cook top. This could result in a gas leak and could causing unsafe operation, which could lead to an increased risk of injury and/or damage to property.

### Inspection & Repair

1. Turn off LP Gas at Both tanks.
2. Remove grates and set aside.



3. Lay masking tape along the edge to prevent damage to the counter top.

- Using a utility knife run the knife along the 3 edges to cut loose the butyl tape.



- Softly pry up the edges of the cook top and lift off counter.



6. Remove the LP hose, be sure to use a back-up wrench to hold valve to prevent damage.




7. Tighten the fitting on the end of the flexible gas connector.



8. Install one end of the flexible gas connector to the LP hose and the other to the cook top. Be sure to hold the valve with a back-up wrench to prevent damage.



9. Bend or flex the flexible gas connector so that it is against the bottom of the cook top.



10. Perform gas drop pressure test, before securing cook top to counter.  
Time for test included with repair
11. Install butyl tape and secure cook top to counter top, and remove masking tape.



**Parts**

Flexible gas connector, butyl rope tape. Part # 0270048

**Tools**

13/16 wrench, back-up wrench, razor knife, masking tapes, and plastic pry tool.

**Warranty**

File Recall Repair warranty claim using warranty code 99.01.33.A for .6 hours

\*Note: photos are for illustration purposes only and might not be representative of the RV be repaired.

**Please refer all questions and authorization requests to Heartland Dealer Services  
Department 877-262-8032**